



翔名科技股份有限公司
Feedback Technology Corp.

製造-營運主管會議


簡報人：劉金勳

Date: 2026.09.22

衛星工廠進度追蹤

- 衛星工廠總表(附件)
- 衛星工廠進度分析


1. FAI合格已派工-件數



2. FAI合格已派工-已交貨PCS




3. FAI待驗證-件數



4. FAI已派工逐日累積件數



5. FAI已派工逐日累積PCS數



6. FAI待驗證逐日累積件數



教育工廠進度追蹤

● 教育工廠

1. 量具設備使用



2. 面板功能介紹操作



3. 手輪操作

4. 每日驗收學習進度

FB 翔名科技股份有限公司
教育訓練簽到表

文件編號: P-07-008

課程名稱	製造新進人員教育訓練		授課單位	☐ 外聘講師 單位: ☒ 內部講師 部門:製造處		
主辦部門	產品開發部		講師姓名	陳序宇		
上課日期	2026.09.17		上課時間	1000-1200		
評核方式 (請打勾選)	☐ 無 ☐ 筆試 ☒ 實作 ☐ 口試 ☐ 心得報告 ☐ 證書		講 師 簽 名			
序 號	部 門	工 號	姓 名	簽 名	評 核 合格 不合格	備 註
1	石基課	2607007	吳俊	吳俊	✓	
2	石基課	2609004	卡爾	卡爾	✓	
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						

課程名稱	製造新進人員教育訓練	授課單位	☐ 外聘講師 單位： ☒ 內部講師 部門：製造處			
主辦部門	產品開發部	講師姓名	陳序宇			
上課日期	2026.09.21	上課時間	1000-1200			
評估方式 (請打勾選)	☐ 無 ☐ 筆試 ☒ 實作 ☐ 口試 ☐ 心得報告 ☐ 證書		講 師 簽 名			
序 號	部 門	工 號	姓 名	簽 名	評 核 合格 不合格	備 註
1	石基課	2607007	吳俊	吳俊	✓	
2	石基課	2609004	卡爾	卡爾	✓	
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						

教育工廠進度追蹤

● 教育工廠

1. 量具設備使用



2. 面板功能介紹操作



3. 手輪操作

4. 每日驗收學習進度

FB 翔名科技股份有限公司
教育訓練簽到表

文件編號: P-07-008

課程名稱	製造新進人員教育訓練		授課單位	☐ 外聘講師 單位: ☒ 內部講師 部門:製造處		
主辦部門	產品開發部		講師姓名	陳序宇		
上課日期	2026.09.17		上課時間	1000-1200		
評核方式 (請打勾選)	☐ 無 ☐ 筆試 ☒ 實作 ☐ 口試 ☐ 心得報告 ☐ 證書		講 師 簽 名			
序 號	部 門	工 號	姓 名	簽 名	評 核 合格 不合格	備 註
1	石基課	2607007	吳俊	吳俊	✓	
2	石基課	2609004	卡爾	卡爾	✓	
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						

課程名稱	製造新進人員教育訓練	授課單位	☐ 外聘講師 單位： ☒ 內部講師 部門：製造處			
主辦部門	產品開發部	講師姓名	陳序宇			
上課日期	2026.09.21	上課時間	1000-1200			
評估方式 (請打勾選)	☐ 無 ☐ 筆試 ☒ 實作 ☐ 口試 ☐ 心得報告 ☐ 證書		講 師 簽 名			
序 號	部 門	工 號	姓 名	簽 名	評 核 合格 不合格	備 註
1	石基課	2607007	吳俊	吳俊	✓	
2	石基課	2609004	卡爾	卡爾	✓	
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						

製造所面臨產能困境

●2026-2028/E 產能缺口50%~70%:

✓ 缺人:

- ✓ 移工人數長期人力不足。
- ✓ 台籍錄取率低於20%以下，技術力仍仰賴10年以上資深員工。
- ✓ 對外薪資吸引力薄弱。

目前移工人力

部門	編制總人數	現有	差額
線切割	11	10	-1
金一	21	18	-3
石墨(含複材)	13	13	0
車床	19	17	-2
金二	36	33	-3
乾式	12	11	-1
濕式	13	12	-1
製造處(含矽加工)	3	3	0
品質管制課	15	15	0
自動化設備工程課	1	1	0
廠務部	1	1	0
行政服務部	1	1	0
加熱工程課(編制外)	2	1	-1
總人數	148	135	-12

產能負荷


	May-26	Jun-26	Jul-26	Aug-26	Sep-26
石墨課	13546	8825	6771	8130	13531
車床課	38303	32159	43800	67482	74147
金屬一課	8939	10460	9878	11661	11320
金屬二課	13051	12480	10512	12256	11330
後處理組	1830	3219	4323	4392	4748
最終檢驗	3951	4458	2641	3508	7015
線切割課	31726	39333	37533	36454	24250

製造所面臨產能困境

✓ 缺地:

✓ 新竹廠可利用土地低於5%→擴張侷限。

A1F




A棟1樓 移機機台圖115.5.4

C3F




C棟三樓新進機台平面圖115.5.24

B1F




C4F




C棟四樓廠房隔間圖現況圖114.5.16

C1F




D1F



D棟1樓熱風機/壓力平衡平台圖115.5.19

D3F



車床C/D棟整合D棟3樓機台位置圖(115.2.22)確認圖

D1F



D棟四層教學中心平面圖114.5/22

製造所面臨產能困境

- ✓ 缺機:
- ✓ 新竹廠區擴張最多只能帶來**15%**產能提升。

材質:其他

We are here

Equipment	Qty	2026	2026	2026	2026	2026	2026	2026	2026	2026	2026	2026	2026	2027	2027	2027	2027	2027	2027	2027	2027
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug
Lathe (Swiss-type)	1															Lathe +23.3 % capacity					
Wire Cut	3																Wire cut +16.4% capacity				
3-axis Milling (Auto)	4																		3 axis Milling +15.1% capacity		
Centerless Grinding	1																			Center Grinding +23.1% capacity	
Lathe (Auto for Ta Rod)	2																				Lathe(Rod) +23.3% capacity

材質:鎢鉬鈹

We are here

Equipment	Qty	2026	2026	2026	2026	2026	2026	2026	2026	2026	2026	2026	2026	2027	2027	2027	2027	2027	2027	2027	2027
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug
Milling (3+1 Axis)	1																				
Milling (3+2 Axis)	1																				
AI ENP (+2 tanks)	1																				
Lathe (Auto)	2																				
Surface Grinder	2																				
5-axis Milling-Turning (Auto)	1																				

✓ 製造五部未來擴張預計可提升8% (1shift)~27% (3shift)。

We are here

製造所面臨產能困境

- ✓ 缺機:
- ✓ 委外預估帶來實質產能提升。

Process	Outsourced (hrs)	AS IS (Utilization)	TO BE (Utilization)	Drop (%)	Remark
Lathe	611	114%	89%	-25%	Capacity restored to healthy operating level
Milling	1489	109%	99%	-10%	Highest outsourced volume; remains near full load.
Multi Axis Milling	652	115%	84%	-31%	Overload resolved; sufficient safety buffer restored.
Turning-Milling	247	98%	80%	-18%	Load reduced further to provide strong operational flexibility.
Surface Grinder	162	112%	80%	-32%	High efficiency reduction; bottleneck successfully eliminated.
Rotary Grinder	1037	118%	84%	-34%	Largest utilization reduction; resolved most severe overload.

製造所面臨產能困境

- ✓ 缺機:
 - ✓ 委外預估帶來實質產能提升。