Field	Value
Document No.	QM-001
Title	Quality Manual
Revision	C
Effective Date	2026-11-05
Prepared By	Shop Owner
Approved By	Jacob Honick, Owner

QM-001 Quality Manual

Status and use of standards. Torchworx LLC is not certified to AS9100, ISO 9001, ISO/IEC 17025, NADCAP or any other quality standard, and does not claim or imply compliance with those standards. References to standards and clause numbers provide guidance and best-practice context only; they are not evidence of certification, full implementation or assessed compliance. Actual customer, contractual and applicable legal requirements remain binding and are reviewed before work is accepted.

This is the single quality manual for Torchworx LLC. It consolidates the basic operating controls and the previously separate development manual. This manual governs where supporting development procedures or templates differ; customer requirements take precedence. A document reference does not establish completed implementation, an activity or an engaged service provider. Certification is a future goal with no formal process or completion date established.

1. QMS Scope and Company Information

1.1 Company Information

Item	Detail
Company Name	Torchworx LLC
Address	1721 63rd ST SE, Everett, WA 98203
Phone	614-670-3079
Owner / Operator	Jacob Honick
Business Type	LLC - Precision CNC and Manual Machining

Item	Detail
Equipment	CNC lathe: CTMACH CQ6133; CNC mill: 3040 three-axis CNC mill (Mach3 control); manual mill: Grizzly G0704
E-mail	torchworxjacob@gmail.com
Owner / sole employee	Jacob Honick; performs management, production, inspection and quality functions
Experience / formation	Workshop operated for more than 10 years; Torchworx LLC formed 2025-03-05
Ownership	US-owned single-member LLC; owner is a US citizen by birth
Certification status	None held; no quality-standard compliance claimed. AS9100 / ISO 9001 are future goals only

1.2 Scope of the Quality Management System

This Quality Management System covers precision CNC and manual machining services for customers in a variety of industries. Torchworx LLC machines metallic or non-metallic parts using CNC milling, CNC turning and manual milling to customer-supplied drawings, specifications and purchase order requirements.

Products and Services Covered:

- CNC milled components (3-axis)
- CNC turned components (2-axis)
- Manually milled components
- Associated inspection, packaging, and shipping services

Scope Limits:

- **Explosives and energetic materials.** None are manufactured, stored, used or transported.
- **Flight hardware.** The current scope is development and test hardware. Flight-critical or safety-critical product would need a separate contract review and may need added controls before it is accepted.

Locations Covered:

- Single facility at the address above - all operations performed on-site except where contracted services are noted

Guidance and Best-Practice References:

- AS9100 Rev D (EN/JISQ 9100:2016), for guidance only
- ISO 9001:2015, for guidance only

These references do not assert certification or compliance. Specific standard provisions become job requirements only when applicable through the customer order, contract or law; such requirements are reviewed and met for that work.

2. Context of the Organization

2.1 Understanding the Organization and Its Context

The organization operates as a single-member LLC providing precision machining services to customers in a variety of industries. The context analysis considering internal and external issues affecting the QMS is documented in QF-032 Context Analysis.

Key Internal Factors:

- Single-person operation - all roles consolidated
- Three-machine shop providing milling and turning capability
- Capacity limited by single-operator constraint
- Direct control over all processes (no delegation complexity)

Key External Factors:

- Customer flow-down requirements vary by contract
- Regulatory requirements (FAA, ITAR as applicable)
- Supply chain risks for raw materials and calibration services
- Industry trends toward tighter tolerances and shorter lead times

2.2 Understanding the Needs and Expectations of Interested Parties

Interested Party	Needs and Expectations
Customers	Conforming product, on-time delivery, traceability, required product records (CoC, FAI when specified), communication
Regulatory Bodies	Identification and fulfillment of legal/regulatory requirements applicable to accepted work; no blanket regulatory-compliance claim
Suppliers	Clear requirements, timely payment, fair evaluation
Calibration Service Providers	Equipment access schedules, clear specifications
Potential future certification body	Requirements to be assessed if a formal certification project is undertaken; no registrar engagement or certification audit is claimed

2.3 Determining the Scope of the QMS

The scope boundaries are defined in Section 1.2 above. The scope was determined by considering the internal and external issues (2.1), interested party requirements (2.2), and the products and services delivered.

3. Quality Policy

The quality policy is stated in §3.1 and maintained separately in **QM-002 Quality Policy**. This manual defines the operating controls.

3.1 Quality Policy Statement (Summary)

Torchworx LLC delivers machined parts that meet every drawing and purchase order requirement, on time, with honest records. Requirements are reviewed before work is accepted. Parts are inspected, problems are communicated to the customer, and lessons learned are used to improve shop practices. Torchworx LLC supports the quality philosophy of its customers.

Torchworx LLC commits to reviewing requirements before accepting work, delivering parts that meet the agreed drawing and purchase order requirements, and communicating problems honestly. This policy is a statement of intent and operating expectations, not a claim of certification, full implementation or compliance with a quality-management standard.

1. **Customer requirements** — Review quality, delivery and communication requirements before work is accepted.
2. **Product conformity** — Inspect against agreed drawings, specifications and job requirements; obtain written customer authorization before any permitted deviation.
3. **Ethics and product safety** — Keep honest records, report concerns and prevent unresolved suspect product from being shipped.
4. **Improvement** — Use feedback, inspection results and reviews to improve shop practices.
5. **Applicable obligations** — Identify and meet customer, contractual and legal requirements that apply to the work. Mention of a standard does not create or imply certification or full-standard compliance.

3.2 Communication and Availability

On adoption, the applicable quality policy is made available to persons performing work and communicated as appropriate. Record actual approval, distribution and reviews; this manual does not establish that the policy has been posted or reviewed. QM-002 is the approved companion policy; this manual defines the operating controls.

3.3 Record Retention

Retain quality records for at least 10 years after shipment, or longer when QP-001, the applicable program, customer contract, purchase order or law requires it. Apply the longest applicable period. Section 6.10 governs records and access; do not destroy records while an applicable retention period remains open.

3.4 Code of Conduct

This section serves as the employee manual equivalent for ethics and product conformity. Anyone performing work for Torchworx LLC, now the owner and in future any employee or helper, shall:

1. Record actual measurements and results honestly. Never falsify, back-date or pre-sign a record, certificate, inspection result or approval.
2. Never ship a part known or suspected not to conform without the customer's written authorization.
3. Disclose defects, mistakes and potential conflicts of interest promptly, including after shipment.
4. Protect customer drawings, data and property and use them only for the customer's order.
5. Stop work when conformity, identification or safety is uncertain, and resolve the question before continuing.
6. Treat "development" or "prototype" status as no licence to deviate from the drawing or purchase order.

3.5 Contribution to Product Safety and Conformity

Contributions to product conformity and safety include: working to the correct drawing revision, keeping parts and material identified, using suitable instruments, recording results accurately, reporting errors, and keeping suspect product from being shipped.


3.6 Acknowledgment

The owner signs and dates an acknowledgment of Sections 3.4 and 3.5 on QF-016 Training Record when this manual is adopted and after each revision. Any future employee signs it before starting work.

4. Process Interaction and Document Cross-Reference

4.1 Process Interaction Map

The QMS processes interact as a system. The following map shows the primary process groups and their relationships for this 3-machine shop (CNC Mill, CNC Lathe, Manual Mill):



```
| MANAGEMENT REVIEW |  | CUSTOMER          |
| (QP-012)          |  | COMMUNICATION     |
+-------------------+  | (QP-023)          |
                       +-------------------+
```

Process Interactions Summary:

- Customer requirements flow in through Contract Review and flow out through Final Inspection/Release
- Purchasing feeds into Receiving Inspection which feeds into Production
- All operational processes are supported by Document Control, Calibration, Training, Risk Management, PM, and FOD Prevention
- Nonconformances and corrective actions provide feedback loops to all processes
- Management Review and Internal Audit provide system-level oversight

4.2 Procedure Cross-Reference Table

The following development procedures are cross-referenced to AS9100 clauses for guidance and navigation only. This table does not establish conformity, implementation or compliance with any clause:

Doc No.	Title	AS9100 Guidance Reference
QP-001	Document Control	7.5 Documented Information
QP-002	Contract Review	8.2 Requirements for Products and Services
QP-003	Purchasing and Supplier Management	8.4 Control of Externally Provided Processes
QP-004	Receiving Inspection	8.4 Control of Externally Provided Processes
QP-005	Production Planning and Control	8.1 Operational Planning and Control
QP-006	In-Process Inspection	8.5.1 Control of Production and Service Provision
QP-007	Final Inspection and Release	8.6 Release of Products and Services
QP-008	Nonconforming Product Control	8.7 Control of Nonconforming Outputs
QP-009	Corrective Action	10.2 Nonconformity and Corrective Action
QP-010	Calibration	7.1.5 Monitoring and Measuring Resources
QP-011	Internal Audit	9.2 Internal Audit
QP-012	Management Review	9.3 Management Review
QP-013	Training and Competence	7.2 Competence
QP-014	Risk Management	6.1 Actions to Address Risks and Opportunities
QP-015	Configuration Management	8.1 Operational Planning and Control
QP-016	Counterfeit Parts Prevention	8.1.4 Counterfeit Part Prevention

Doc No.	Title	AS9100 Guidance Reference
QP-017	Product Safety	8.1.3 Product Safety
QP-018	FOD Prevention	7.1.4 Environment for the Operation of Processes
QP-019	Preventive Maintenance	7.1.3 Infrastructure
QP-020	Handling, Storage, Packaging, and Shipping	8.5.4 Preservation
QP-021	Customer Property	8.5.3 Property Belonging to Customers or External Providers
QP-022	First Article Inspection	8.5.1 Control of Production and Service Provision
QP-023	Customer Communication	8.2.1 Customer Communication
QP-024	Work Transfer	8.1 Operational Planning and Control
QP-025	Control of Changes	6.3 Planning of Changes

4.3 Form Cross-Reference Table

The following blank forms/templates are available for development and use as applicable. A listed form is not evidence of a completed activity:

Doc No.	Title	Associated Procedure
QF-001	Contract Review Checklist	QP-002
QF-002	Purchase Order	QP-003
QF-003	Receiving Inspection Record	QP-004
QF-004	Job Traveler	QP-005
QF-005	In-Process Inspection Record	QP-006
QF-006	Final Inspection Report	QP-007
QF-007	FAI Form 1 - Part Number Accountability	QP-022
QF-008	FAI Form 2 - Product Accountability	QP-022
QF-009	FAI Form 3 - Characteristic Accountability	QP-022
QF-010	Certificate of Conformance	QP-007
QF-011	Nonconforming Material Report	QP-008
QF-012	Corrective Action Request	QP-009
QF-013	Internal Audit Checklist	QP-011
QF-014	Internal Audit Report	QP-011
QF-015	Management Review Minutes	QP-012
QF-016	Training Record	QP-013

Doc No.	Title	Associated Procedure
QF-017	Supplier Evaluation	QP-003
QF-018	Supplier Scorecard	QP-003
QF-019	Approved Supplier List	QP-003
QF-020	Calibration Log	QP-010
QF-021	Preventive Maintenance Record	QP-019
QF-022	Customer Complaint	QP-023
QF-023	Risk Register	QP-014
QF-024	Customer Property Log	QP-021
QF-025	Document Change Request	QP-001
QF-026	FOD Checklist	QP-018
QF-027	Equipment List	QP-019
QF-028	Measurement Equipment List	QP-010
QF-029	Change Notification	QP-025
QF-030	Calibration Schedule	QP-010
QF-031	Suspect/Counterfeit Part Report	QP-016
QF-032	Context Analysis	QM-001
QF-033	Out-of-Tolerance Impact Assessment	QP-010
QF-034	Supplier Audit Checklist	QP-003
QF-035	Supplier Corrective Action Request	QP-003
QF-036	Training Matrix	QP-013
QF-037	Quality Objectives Tracker	QM-003
QF-038	Improvement Log	QP-012

5. Organizational Structure and Responsibilities

5.1 Organization Overview

This is a single-member LLC. The Owner fulfills all management and operational roles. There is no delegation of authority to employees because there are no employees. External services may be arranged where needed for the accepted work; no provider engagement is established by this manual.

The owner is the sole employee and is responsible and accountable for every activity in this manual: contract review, purchasing, production, inspection, product release, non-conformance disposition, calibration, document control and corrective action. Because one person makes and inspects the product, Section 6.7 adds deliberate safeguards: written inspection plans, recorded actual values, and a review of the completed job packet before release.

The owner's competence comes from more than 10 years of operating this workshop. New skills, methods or equipment are recorded on QF-016 when used for customer work. Work outside demonstrated competence is not accepted unless the competence is gained or the work is bought from a qualified, customer-approved source.

5.2 Roles Fulfilled by Shop Owner

Role	QMS Responsibilities
Top Management	Establish quality policy and objectives, ensure QMS integration with business processes, ensure resources are available, promote improvement and risk-based thinking
Quality Manager	Maintain the QMS, ensure process conformance, report QMS performance, ensure customer focus throughout the organization
Management Representative	Interface with customers and any actually engaged external parties on quality matters
Production Operator	Set up and operate CNC Mill, CNC Lathe, and Manual Mill per work instructions and job travelers
Inspector	Perform receiving, in-process, and final inspection per procedures; make accept/reject decisions
Internal Auditor	Coordinate reviews and any independent audits actually required or arranged under 5.3; an owner self-check is not represented as an independent AS9100 audit
Purchasing / Buyer	Select and evaluate suppliers, issue purchase orders with quality requirements, manage ASL
Document Controller	Control document creation, revision, distribution, and obsolescence
Calibration Coordinator	Schedule calibration, maintain calibration records, manage OOT conditions
Shipping / Receiving	Receive incoming material, verify against PO; package and ship finished product

5.3 External Services and Reviews

External services are selected for the actual job or business need. This section describes possible arrangements, not existing contracts, completed audits, accreditation or compliance with a quality standard.

Activity	Approach	Customer and capability considerations
Calibration / verification	In-house checks using known-good standards where permitted, or an appropriate external service under QP-010	Meet customer-required methods, traceability, certification and accreditation; no accredited calibration is claimed without evidence
Quality reviews / audits	Owner reviews under §6.11; an independent reviewer or auditor may be engaged when required or specifically arranged	Owner self-checks are not independent audits. No annual auditor contract, AS9100 audit or completed assessment is claimed
Special processes	Review capability and any external source before accepting the work	Obtain customer approval where required; use NADCAP-accredited or otherwise qualified sources when the actual contract/specification requires them. No process approval or accreditation is implied
IT / backup	Owner-managed storage and backup, with external support if actually arranged	Follow documented practices and customer data requirements; retain evidence of actual backup/retrieval checks. No IT service contract is asserted

AS9100, ISO 9001 and other standard references are guidance and best-practice resources. If a customer imposes specific requirements, review and satisfy those requirements for the affected work; this does not establish organization-wide standard compliance or certification.

5.4 Authority and Communication

Authority Structure:

- The Shop Owner manages shop quality decisions within contractual and legal limits, including product release and nonconformance control. Repair, use-as-is or deviations require prior written customer authorization; no customer MRB authority is implied.
- Supplier approval and removal
- Corrective action approval and effectiveness verification
- Process changes and document revisions
- Stop-work authority for quality or safety concerns

Internal Communication:

- As a single-person operation, internal communication is inherent
- Documented decisions (NCR dispositions, CARs, management review minutes) serve as the formal record
- QMS changes are effective immediately upon document revision approval

External Communication:

- Customer communication per QP-023

- Supplier communication per QP-003
- Communication with a registrar only if a certification project is actually initiated

5.5 Responsibility Matrix

QMS Process	Shop Owner	External Calibration Provider, if used	Independent Auditor, if engaged	Special Process Suppliers, if used
Document Control (QP-001)	R, A	-	-	-
Contract Review (QP-002)	R, A	-	-	-
Purchasing (QP-003)	R, A	-	-	-
Receiving Inspection (QP-004)	R, A	-	-	-
Production Planning (QP-005)	R, A	-	-	-
In-Process Inspection (QP-006)	R, A	-	-	-
Final Inspection (QP-007)	R, A	-	-	-
Nonconforming Product (QP-008)	R, A	I	-	I
Corrective Action (QP-009)	R, A	I	-	I
Calibration (QP-010)	R, A	R when used	-	-
Reviews / audits (QP-011 development reference; §6.11 current controls)	Coordinate; R, A for owner self-checks	-	R if engaged for an independent audit	-
Management Review (QP-012)	R, A	-	-	-
Training (QP-013)	R, A	-	-	-
Risk Management (QP-014)	R, A	-	-	-
Configuration Mgmt (QP-015)	R, A	-	-	-
Counterfeit Prevention (QP-016)	R, A	-	-	-
Product Safety (QP-017)	R, A	-	-	-
FOD Prevention (QP-018)	R, A	-	-	-
Preventive Maintenance (QP-019)	R, A	-	-	-
Handling/Storage/Shipping (QP-020)	R, A	-	-	-
Customer Property (QP-021)	R, A	-	-	-
First Article Inspection (QP-022)	R, A	-	-	-
Customer Communication (QP-023)	R, A	-	-	-

QMS Process	Shop Owner	External Calibration Provider, if used	Independent Auditor, if engaged	Special Process Suppliers, if used
Work Transfer (QP-024)	R, A	-	-	-
Control of Changes (QP-025)	R, A	-	-	-

Legend: R = Responsible (does the work), A = Accountable (approves/owns), I = Informed. External assignments apply only when a provider is actually engaged; this matrix is not evidence of a contract or standard compliance.

6. Operating Controls

6.1 Customer Data and Export-Controlled Information

Torchworx LLC is **not registered with the DDTC under ITAR** and **does not accept ITAR-controlled work or technical data.** The sole operator is a US person. If a document marked ITAR, EAR-controlled, CUI or Distribution-limited is received, work stops, the data is not shared further, and the customer is contacted for direction.

Torchworx LLC has **not performed a NIST SP 800-171 self-assessment**, has no POAM and no SPRS score, and therefore **does not accept orders that flow down DFARS 252.204-7012 with CUI** until it has done so. Ordinary customer drawings and data are stored only on the owner's password-protected devices and accounts. They are not shared with anyone except the customer, or a supplier approved by the customer who needs them for the order.

6.2 Document Control

1. Each controlled document carries an identifier, title, revision letter, effective date and approval.
2. Changes are made by revising the document, recording what changed in its revision history, and having the owner approve and date it. QF-025 Document Change Request is used for significant changes.
3. The current revision of each document is listed in the Master Document List. Superseded copies are removed from use, or marked "OBSOLETE" when kept for reference.
4. **Customer drawings and specifications** are logged by part number and revision when received. They are checked against the purchase order (Section 6.3) and kept in the job folder as the only working copy. When the customer issues a revision change, the old copy is marked obsolete and withdrawn, and the effect on work in process is reviewed.

5. CNC programs are identified by part number and revision and linked to the job traveler.

6.3 Contract Review — Customer Orders and Changes

Before accepting any RFQ, purchase order or change, the owner completes QF-001 Contract Review Checklist and confirms:

- part number, drawing and specification revisions match the purchase order;
- material, condition and certification requirements;
- all dimensions and notes can be produced **and measured** with suitable equipment;
- quantity and delivery are achievable;
- quality clauses and flowdowns, including CoC, material certs, FAI, traceability, record retention, packaging, source inspection, right of access, export control, DFARS and CUI clauses;
- any outside processing needed.

Conflicts or unclear requirements are resolved with the customer in writing **before** acceptance. Purchase order changes are reviewed the same way and recorded on QF-001 or QF-029. Acceptance is recorded by signed and dated acknowledgment of the purchase order.

6.4 Purchasing and Supplier Control

6.4.1 Supplier Selection and Approval

Suppliers of material, tooling that affects conformity, calibration services and outside processing are evaluated and listed on QF-019 Approved Supplier List, with the scope each supplier is approved for. The basis for approval is recorded on QF-017: certification such as ISO 9001, AS9100, ISO/IEC 17025 or NADCAP where relevant, ability to supply the required certifications, past performance, or customer direction. Customer-directed sources are used where specified.

Raw material is bought from the mill or an established distributor able to supply material certifications. Torchworx LLC does not buy material from unknown brokers.

6.4.2 Purchase Orders to Suppliers

Purchase orders, issued on QF-002 or as a documented online order, state the item, material specification and condition, quantity, required certifications (CoC, mill or material test report), traceability, and any flowed-down customer requirements. The owner reviews each order for completeness before it is placed.

6.4.3 Receiving

Incoming material is checked against the order and its certifications on QF-003 Receiving Inspection Record. Material without the required certification is held until the certification is received. Mixed, unidentified or suspect material is not used.

6.4.4 Counterfeit Prevention

Material and parts are bought only from the manufacturer, the mill or authorized distributors. Suspect items are segregated and reported to the customer.

6.5 Material Identification, Traceability, Storage and Preservation

1. Each lot or heat of raw material receives an internal lot ID on receipt. The lot ID is linked to the supplier's lot or heat number and certification on QF-003.
2. Raw material, cut blanks, work in process and finished parts stay identified at all times by job number and material lot, using tags, labeled containers, bags or trays. When parts must be traceable individually, each piece or tray position is linked to its inspection record. Parts are not marked unless the drawing or the customer permits it.
3. The job traveler (QF-004) records the material lot, quantities started, scrapped and shipped, so that every shipped part traces back to its material certification.
4. Areas are separated for incoming/raw material, work in process, finished parts awaiting shipment, and a clearly marked **HOLD** area for nonconforming or suspect items.
5. Material and parts are protected from damage, corrosion, contamination and mix-up. Burrs and chips are removed, parts are cleaned, and they are packaged to prevent contact damage in transit. Customer packaging requirements are followed.
6. Customer-supplied material and property are identified, checked on receipt, protected, and recorded on QF-024. Loss or damage is reported to the customer.

6.6 Measuring Equipment and Calibration

1. Only instruments with a current calibration and a recorded fitness for the tolerance being checked are used to accept product. Each acceptance instrument has an ID, is listed on QF-028 Measurement Equipment List, and has a due date on QF-030.

2. Calibration or verification may be performed in-house by the owner using known-good standards where customer requirements permit, or by an appropriate external service. The approach is selected for the equipment and intended work under QP-010. No dedicated caliper form or fixed in-house reference values are prescribed. Record the activity and result on QF-020 or a linked equipment/job record.

Customer requirements govern certification, traceability, accreditation, methods, intervals and reporting. Use the required external service or other specified approach when necessary; obtain written customer approval for alternatives. No certified, accredited or traceable calibration is claimed without supporting evidence.

3. Instruments are labeled with ID, calibration date and due date, and with their scope where limited. An instrument not yet released is labeled "NOT FOR ACCEPTANCE".

4. Equipment condition and suitability are checked before use, with any additional checks required for the job. A failed check, damage or an overdue date takes the instrument out of use immediately. Product measured with it since the last good check is reassessed on QF-033, and the customer is told if shipped product may be affected.

5. Calibration events are recorded on QF-020 Calibration Log, and certificates are filed by instrument ID.

6. Steel rules and similar tools used only for layout are marked "Reference Only" and never used to accept product.

6.7 Production and Inspection

6.7.1 Planning

Each job has a traveler (QF-004) listing the operations, drawing revision, material lot, program revision, tooling, and inspection hold points. Inspection characteristics, methods and instruments are planned before production starts.

6.7.2 First-Piece, In-Process and Final Inspection

1. **First piece:** the first part of each setup, and after any setup, program or tool change that can affect a feature, is fully inspected to the drawing and recorded on QF-005 before production continues.
2. **In-process:** the planned characteristics are checked at the hold points on the traveler.
3. **Final:** every drawing and purchase order characteristic is verified and recorded on QF-006 before release.
4. **No sampling.** Torchworx LLC does not use sampling plans such as MIL-STD-1916 or ANSI Z1.4. **Every part is inspected (100%) for every drawing and purchase order acceptance characteristic** unless the customer approves a different plan in writing. This is practical for low-volume work.

5. **Actual values** are recorded, not just "OK", for each dimensional characteristic, together with the instrument ID, date and inspector. A result is never rounded into tolerance. Results too close to a limit to decide reliably, given the measurement capability, are placed on hold for better measurement.
6. Where a feature cannot be verified with available equipment, a qualified, customer-approved inspection service is used or the method is agreed with the customer **before** the order is accepted.
7. An AS9102 First Article Inspection is performed only when the purchase order requires it.

6.7.3 Production Tooling

1. Job-specific or customer-owned fixtures, gauges, soft jaws and special tools that affect conformity get an ID and an entry in the Tooling Register. The entry records description, owner, part number and revision, storage location, condition, any maintenance or check requirement, last check, and return or disposition.
2. Tooling is checked for identity, condition and suitability before use. The check is noted on the traveler.
3. Stored tooling is cleaned, protected from corrosion and damage, and labeled. Tooling records are kept for the period in Section 6.10.
4. Damaged or suspect tooling is tagged and set aside, and work made with it is assessed. Customer-owned tooling is not modified, repaired or scrapped without the customer's direction.
5. General-purpose cutters and holders are controlled through the setup and tool list in the job packet rather than individually.

6.7.4 Release and Certificate of Conformance

Before shipment the owner reviews the completed job packet: traveler, inspection records, material certifications, and any resolved nonconformances and customer authorizations. Release is signed on QF-006. A **Certificate of Conformance** (QF-010), signed by the owner as the authorized representative, states that the parts conform to the purchase order and drawing requirements and references the material certification. Copies of material certifications are supplied when required. A CoC is never signed for unverified or unresolved product.

6.8 Nonconforming Product (MRB)

1. A failed or suspect part is identified immediately with a red **REJECTED** hang tag bearing the QC person’s initials, inspection date and part number (WI-008), moved to the HOLD area, and recorded on QF-011 Nonconforming Material Report.
2. The owner acts as the Material Review authority and may decide only the following:
    - **rework** to meet the original drawing, followed by full reinspection; or

    - **scrap**.
3. **Use-as-is, repair, or any deviation from the drawing requires the customer's prior written approval.** Torchworx LLC holds no customer MRB authority. The approval is kept in the job file and referenced on the CoC.
4. If nonconforming product may already have been shipped, the customer is notified in writing within one business day of discovery.
5. Nonconforming parts that are scrapped are made unusable so they cannot re-enter production.

6.9 Corrective and Preventive Action

1. **Corrective action** (QF-012) is opened for customer complaints, escapes, repeat nonconformances and any issue judged significant. It records containment, root cause (for example 5-Why), the correction, a check of other affected work, and verification that the action worked. Customer-requested corrective action responses are provided within the customer's requested time.
2. **Preventive action:** risks to conformity and delivery are reviewed during contract review and before first production of a new part. Examples are tight tolerances, measurement limits, material availability and single-operator capacity. Actions are recorded on QF-023 Risk Register with owner and due date.
3. Corrective actions are entered in the NCR/CAR Log and reviewed in Section 6.11.

6.10 Records, Retention and Access

1. Quality records include the contract review, purchase orders, material certifications, travelers, inspection records, NCRs and customer authorizations, CoCs, calibration records, tooling records, and training acknowledgments. They are filed by job number and customer, or by instrument or tool ID.
2. Records are kept legible and complete, are corrected only by a dated, initialed change that leaves the original readable, and are protected from loss. Electronic records are stored on the administrative computer at the Torchworx LLC facility and backed up to an external hard drive weekly, and also whenever documents or records are added or changed. A test retrieval from the backup drive is made at least once a year.
3. **Retention:** at least **10 years** after shipment, or longer if QP-001, the applicable program, contract, purchase order or law requires it. Calibration records are kept for the life of the instrument plus 3 years, or longer if another applicable period requires it. Apply the longest period; records are not destroyed while any applicable retention period still runs.
4. **Access:** inspection and quality records are available for review by the customer's Quality Assurance personnel, the customer's customers, and government agencies, as the contract requires. Information about other customers is protected.

6.11 Monitoring, Review and Improvement

1. At least every quarter in which customer work is performed, the owner reviews on-time delivery, rejects and returns, NCRs and corrective actions, customer feedback, calibration status and supplier performance. The review and the actions decided are recorded on QF-015 (brief minutes are enough).
2. Once a year the owner checks the shop's actual practice against this manual and records the gaps and actions on QF-038. This self-check is not independent, and it is not represented as an AS9100 internal audit.
3. Customers are notified before any change that could affect their product: change of location, of a key process or process supplier, or of ownership.

6.12 Flowdown to Suppliers

Applicable customer requirements are flowed down on purchase orders to suppliers whose work affects the customer's product. These include specifications, certifications, traceability, right of access and record retention. Outside processing is not used without the customer's agreement when the purchase order restricts it.

7. References

Quality-standard references below are guidance and best-practice resources only. They do not claim certification or compliance; customer-imposed requirements are reviewed for the applicable job.

- QM-002 Quality Policy
- QM-003 Quality Objectives
- QF-032 Context Analysis
- QF-037 Quality Objectives Tracker
- AS9100 Rev D (EN/JISQ 9100:2016)
- ISO 9001:2015

8. Revision History

Rev	Date	Description	Approved By
-	2025-07-14	Initial draft	Shop Owner
A	2026-08-10	Revised: updated Clause 8.3 non-applicability terminology, added record retention statement, corrected procedure cross-reference table (QP-017 clause mapping), removed duplicate sections, incorporated full procedure and form cross-reference tables	Shop Owner

Revision B, approved and effective 2026-11-05: broaden industry/material scope; remove §1.3; make guidance-only status explicit; revise policy, external-service and responsibility wording; align calibration and retention with current basic controls. Approved by Jacob Honick, Owner, by explicit instruction in the project conversation. Earlier revision-history entries describe superseded wording.

Revision C, approved and effective 2026-11-05: consolidate the separate quality manuals and superseded scope addendum into this single manual; retain session revisions and remap supporting references. Approved by Jacob Honick, Owner, by explicit instruction in the project conversation; no handwritten signature is implied. Revision B remains in history.