Field	Value
Document No.	QP-004
Title	Receiving Inspection
Revision	B
Effective Date	2026-08-10
Prepared By	Owner
Approved By	Jacob Honick, Owner
Revision Approval Date	2026-11-05
Next Review	2027-08-10

QP-004 Receiving Inspection

Standards and clause references are guidance only and do not claim certification or standard compliance. Applicable customer, contractual and legal requirements govern accepted work.

1. Purpose

Define the process for inspecting and verifying incoming material, parts, and outside-processed items to ensure conformance to purchase order requirements before release to stock or production.

2. Scope

Applies to all incoming raw material, hardware, outside-processed parts (heat treat, plating, NDT), and subcontracted machining received at the shop.

3. Responsibilities

Role	Responsibility
Shop Owner	Perform receiving inspection on all incoming material. Accept or reject material based on verification results. Maintain receiving inspection records. Quarantine nonconforming material.

4. References

- QF-003 — Receiving Inspection Record
- WI-007 — Incoming Material Verification
- QP-003 — Purchasing and Supplier Management
- QP-008 — Nonconforming Product Control
- QP-016 — Counterfeit Parts Prevention
- AS9100 Rev D Clause 8.4.3

5. Definitions

- **Certified Material Test Report (CMTR):** Mill-issued documentation certifying material chemical composition and mechanical properties to the applicable specification.
- **Quarantine:** Segregation of material in a designated hold area pending disposition of a nonconformance.

6. Procedure

Receipt and Identification

1. Upon receipt, compare the packing slip to the purchase order (QF-002) for correct part number, material specification, quantity, and revision.
2. Verify the supplier is on QF-019 within the applicable customer-approved scope under QP-003. If not, hold the material and do not proceed until resolved.
3. Assign a receiving number or lot identifier for traceability. Maintain the identifier on an attached material tag under WI-007; do not use direct marker identification.

Documentation Review

1. Verify the documentation required by the actual order/customer is present and complete, following WI-007 for raw material. Apply the following as applicable:
    - Certificate of Conformance (C of C) from the supplier
    - Certified Material Test Report (CMTR) for raw material, showing chemical and mechanical properties meet the specification
    - Process certifications for outside processing (heat treat, plating, NDT reports)
    - Traceability data (heat lot, batch number) matching the physical material markings
2. Confirm test report values meet the specification requirements (not just that a cert is present).

Physical Verification

1. Perform visual inspection for damage, contamination, corrosion, or incorrect packaging.

2. Verify material identification markings match the CMTR and purchase order (heat number, alloy, size).
3. Full receiving inspection is the default: verify every received piece for all applicable acceptance characteristics, including specified dimensions. A different extent requires a customer-specified or customer-approved written plan in the job record. Review lot-based material/process documentation for every applicable lot.
4. For outside-processed parts, verify visual appearance is consistent with the process specification (color, coating uniformity, marking legibility).

Counterfeit Detection

1. Check for indicators of suspect/counterfeit material:
   - Missing or inconsistent heat lot markings
   - Documentation anomalies (mismatched fonts, missing mill logos, photocopied certs without original traceability)
   - Material appearance inconsistent with specification (wrong color, weight, or surface finish for the alloy)
2. If counterfeit material is suspected, quarantine immediately and follow QP-016.

Acceptance or Rejection

1. If all checks pass, record results on QF-003 Receiving Inspection Record and mark the material as accepted. Release to stock or production.
2. If any check fails:
   - Quarantine the material in the designated hold area.
   - Initiate a Nonconforming Material Report (QF-011) per QP-008.
   - Notify the supplier per QP-003.
   - Do not release material to production until disposition is complete.

Urgent/Released-to-Production Material

1. Material shall NOT be released to production prior to completing receiving inspection unless a documented customer-authorized concession exists.
2. If material is released before inspection completion under concession, identify it with "UNINSPECTED" marking and record the concession authorization on QF-003.

7. Records Generated

Form No.	Title	When Completed
QF-003	Receiving Inspection Record	For every incoming shipment of material or outside-processed parts

8. Revision History

Rev	Date	Description	Approved By
A	2026-08-07	Initial release	Shop Owner

Revision B Approval

Approved 2026-11-05 by Jacob Honick, Owner. Standardize control metadata and annual review, remove fixed page counts and align applicable references and wording.