Field	Value
Document No.	WI-008
Title	Part Marking
Revision	C
Effective Date	2026-08-10
Prepared By	Owner
Approved By	Jacob Honick, Owner
Revision Approval Date	2026-11-05
Next Review	2027-08-10

WI-008 Part Marking

1. Purpose

Define the hang-tag method used by Torchworx LLC to identify parts and show inspection status without permanently marking the part.

2. Scope

Incoming raw-stock identity and yellow HOLD material-control status are addressed in WI-007. Inspection-status tags remain green INSPECTED or red REJECTED. When raw stock has no assigned part number, WI-007 requires a dash in that field and a traceable material/lot reference; finished-part tags require the actual part number.

Applies to parts identified and inspected by Torchworx LLC. The standard method is a hang tag attached to the individual part. A tag supplements the job traveler and inspection records; it does not replace material-lot, drawing-revision, serial-number or other traceability required for the job.

Additional customer requirements that differ from this part-marking strategy shall be reviewed, approved and put into use for the relevant jobs before the affected work or delivery. Record the requirements and approval in the job packet. Customer drawing, purchase order and specification requirements take precedence; obtain the customer's written authorization before using an alternative to a customer requirement.

3. Required Materials and Records

- Green hang tags labeled **INSPECTED**
- Red hang tags labeled **REJECTED**
- Suitable ties or other non-damaging tag attachments
- Pen or other durable writing method
- Current customer drawing, purchase order and applicable specifications
- QF-004 Job Traveler and applicable inspection records

4. Tag Content and Attachment

Every green INSPECTED or red REJECTED tag shall show:

- Part number
- QC person's initials
- Date of inspection

Write all entries legibly. Use the actual inspection date and the initials of the person who performed the inspection. The owner may act as the QC person.

Attach the tag securely to the part so it remains associated with that part during handling and storage. Use a location and attachment that do not scratch, distort, contaminate or interfere with the part. Do not attach loose tags near moving machinery; remove or secure attachments before machining and preserve part identity through the traveler and identified storage.

Where a customer requires additional identification, include the required information and method in the job instructions. Maintain job, lot and individual-piece linkage in the traveler and inspection record as applicable; the part number alone does not establish that traceability.

5. Procedure

1. Review the current drawing, purchase order and job traveler for identification and marking requirements. Resolve any conflict with the customer before proceeding.
2. Maintain part identity and inspection status during processing. An uninspected part shall not receive a green INSPECTED tag.
3. Perform the applicable inspection and record the results in the inspection record.
4. For a part that passes the applicable inspection, complete and attach a green tag labeled **INSPECTED**, with the QC person's initials, inspection date and part number. Where further operations or inspection remain, show the completed stage and outstanding steps in the traveler; a green tag does not authorize shipment.

5. For a part that fails inspection, complete and attach a red tag labeled **REJECTED**, with the QC person's initials, inspection date and part number. Remove any conflicting green tag, segregate the part in the HOLD area and record the nonconformance per QP-008/QF-011.
6. Hold any part with uncertain identity or conformity pending review. Do not use a green tag to imply acceptance of an unresolved condition.
7. Verify that the tag is legible, complete, correctly attached and consistent with the part and inspection record. Record tag status and any customer-specific marking completion on QF-004.
8. Before shipment, confirm final inspection and release are complete, required customer marking is present, and tag information agrees with the job packet. A green INSPECTED tag does not replace the signed release or Certificate of Conformance.

6. Acceptance Criteria

- Correct tag color and wording: green **INSPECTED** for passed inspection or red **REJECTED** for failed inspection.
- QC person's initials, actual inspection date and correct part number are present and legible.
- Tag is securely attached to the correct part without damage.
- Tag status agrees with the traveler and inspection results; required traceability remains intact.
- Additional customer marking requirements have been approved, implemented and verified for the job.
- No engraving, stamping, etching or other permanent marking is applied as a shop default. Use permanent marking only under the documented customer requirements and approved job instructions.

7. Incorrect Tags, Rework and Status Changes

1. Hold the affected part if a tag is missing, illegible, incorrect or inconsistent with the inspection record. Verify identity and inspection status before replacing the tag; do not invent missing information.
2. Record corrections or tag replacement in the job record so the original inspection result remains traceable. Remove obsolete or conflicting tags from use.
3. A red REJECTED tag remains the status until authorized disposition and any required rework and reinspection are complete. Rejection is not itself a scrap decision.

4. Following successful reinspection, replace the red tag with a green INSPECTED tag bearing the QC person's initials, actual reinspection date and part number. Keep the original nonconformance and disposition records.
5. Repair, use-as-is or deviation from customer requirements requires prior written customer authorization. Preserve that authorization and identify the disposition in the job packet before release.

8. References

- QP-005 — Production Planning and Control
- QP-007 — Final Inspection and Release
- QP-008 — Nonconforming Product Control
- QF-004 — Job Traveler
- QF-005 — In-Process Inspection Record
- QF-006 — Final Inspection Report
- QF-011 — Nonconformance Report
- WI-006 — Final Part Inspection

9. Revision History

Rev	Date	Description	Approved By
A	2026-08-06	Initial release	Shop Owner
B	2026-11-05	Replace default permanent marking with attached green INSPECTED/red REJECTED hang tags, mandatory tag fields and customer-specific provisions; reconcile inspection and release status. Approved by owner instruction on 2026-11-05	Jacob Honick, Owner

Revision C Approval

Approved 2026-11-05 by Jacob Honick, Owner. Retain green INSPECTED/red REJECTED hang tags and distinguish incoming material HOLD/identity controls.