Absolute Lap Time by Stint Progress
Lines = bin means | Bands = 95% bootstrap CI
Note: Stint length normalized to [0,1]

SOFT (Performance)





MEDIUM (Performance)





HARD (Performance)