

October 8, 2010 LIC-10-0090

U. S. Nuclear Regulatory Commission Attn: Document Control Desk

Washington, DC 20555-0001

Reference: Docket No. 50-285

Subject: Licensee Event Report 2010-005, Revision 0, for the Fort Calhoun

Station

Please find attached Licensee Event Report 2010-005, Revision 0, dated October 8, 2010. This report is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B).

No regulatory commitments are contained in this submittal. If you should have any questions, please contact me.

Sincerely,

Jeffrey A. Reinhart Site Vice President

JAR/rmc

Attachment

c: E. E. Collins, NRC Regional Administrator, Region IV

L. E. Wilkins, NRC Project Manager

J. C. Kirkland, NRC Senior Resident Inspector

INPO Records Center

NRC FO (9-2007)	RM 36	RM 366 U.S. NUCLEAR REGULATORYCOMMISSION								APPROVED BY OMB: NO. 3150-0104 EXPIRES: 08/31/20						
	LIG	(See i	everse for r	IT REPO equired num s for each bi	ber of			recepto to Receinfor Received ma	quest: 80 hrs. ocess and fed the Records gulatory Com ocollects@nro gulatory Affa dget, Washin lection does	en per response Reported lesson back to industry and FOIA/Privat mission, Washing c.gov, and to th irs, NEOB-10202 gton, DC 20503. not display a cuit tor sponsor, and	s learned are. Send comme by Service Bragton, DC 2055 e Desk Office c, (3150-0104). If a means urrently valid O	incorporal ints regard anch (T-5 5-0001, or er, Office b, Office used to im MB contro	ted into ding burn F52), I by inter of Info of Mana apose ar of numb	the licensing den estimate U.S. Nuclear met e-mail to rmation and gement and information er, the NRC		
1. FACILITY NAME Fort Calhoun Station									2. DOCKET NUMBER 3. PAGE 1 0							
4. TITLE		į.	noperabili	ty of the E	merg	ency	Diese	el Gene	rator Fu	el Oil Trans	fer Syste	m				
5. E	VENT D	ATE		R NUMBER		7. R	EPORT	DATE								
MONTH	DAY	YEAR	YEAR		REV NO	MONT H	DAY	YEAR	FACILITY N				050	KET NUMBER		
1	6	2010	2010	- 005 -	00	10	8	2010	FACILITY N	AME			050	00		
9. OPER	RATING	MODE	11, T	HIS REPORT I	S SUBM	ITTED	PURSUA	ит то тн	REQUIREM	IENTS OF 10 CF	R §: (Check a	ll that app	ly)			
1			□ 20.2201(b) □ 20.2203(a)(3)(i □ 20.2201(d) □ 20.2203(a)(3)(i				)(3)(i)	□ 50.73(a)(2)(i)(C) □ 50.73( □ 50.73(a)(2)(ii)(A) □ 50.73(					i)			
							)(3)(ii)						73(a)(2)(viii)(A)			
			□ 20.22	203(a)(1)		□ 2	0.2203(a	)(4)		50.73(a)(2)(ii)	(B) 🗆	50.73	(a)(2)(vi	ii)(B)		
			□ 20.22	203(a)(2)(i)		□ 5	0.36(c)(1	)(i)(A)		50.73(a)(2)(iii)		50.73	a)(2)(ix	)(A)		
10 POV	VERIE	VEI	□ 20.22	203(a)(2)(ii)		□ 5	0.36(c)(1	)(ii)(A)		50.73(a)(2)(iv)	(A) 🗆	50.73	(a)(2)(x)			
10. POWER LEVEL			□ 20.2203(a)(2)(iii) □ 50.36				50.36(c)(2)			50.73(a)(2)(v)	(A) 🗆	73.71(a)(4)				
			□ 20.22	203(a)(2)(iv)		□ 5	0.46(a)(3	3)(ii)		50.73(a)(2)(v)	(B)	73.71	(a)(5)			
	100		□ 20.22	203(a)(2)(v)		<sub>□</sub> 5	0.73(a)(2	?)(i)(A)		50.73(a)(2)(v)	(C) 🗆	OTHE	R			
			□ 20.22	203(a)(2)(vi)			0.73(a)(2			50.73(a)(2)(v)	(D)	Specify or in N	in Abstr	act below 366A		
					12. LI	CENS	EE CON	TACT FO	R THIS LE							
FACILITY	NAME			Erick M	atzke					TELEPH	ONE NUMBER ( 402-	include Are -533-6				
	1.7		13. COMPLE	TE ONE LIN	E FOR	EACH	COMPO	NENT F	AILURE DE	SCRIBED IN T	HIS REPOR	Т				
CAUSE SYST		SYSTEM	COMPONEN T	MANU- FACTURER		ORTABI O EPIX		CAUSE	SYSTE	M COMPONE		MANU- FACTURER		REPORTABLE TO EPIX		
XX Yes	14. SUPPLEMENTAL REPORT EXPECTED  XX Yes (If yes, complete 15. EXPECTED SUBMISSION DATE) NO									15. EXPECTED SUBMISSION			DAY	YEAR		
	( ) 50	, compre		000	0.0	2 (200)				DATE	1		28	2011		

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

Diesel Fuel Oil Transfer Pump FO-37 and its credited portable back-up pump were inoperable on January 6-7, 2010. On January 6, 2010, FO-37 was rendered inoperable due to local area flooding caused by the rupture of FP-772, "Service Building Fire Sprinkler Isolation Valve". The function of FO-37 is to transfer diesel fuel between "Diesel Fuel Oil Storage Tanks" FO-10 and FO-1. On June 24, 2010, an engineering evaluation determined that the credited portable back up pump to FO-37 was not the correct pump for the application and would not transfer diesel fuel oil from FO-10 to FO-1 as intended. Since both pumps (FO-37 and the credited portable back-up pump) were inoperable this is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B).

The root cause of the event is still under investigation and will be reported in a supplement to this LER

The originally credited portable back-up pump was replaced with a new portable pump that has the capability to transfer diesel fuel oil between tanks FO-10 and FO-1. The appropriate procedures were revised to address the pump replacement.

2011

NRC FORM 366A (9-2007)

# LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

U.S. NUCLEAR REGULATORY COMMISSION

1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE		
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	2	OF 3
ort Camoun Station	03000283	2010	005 -	00		OF 3

#### **NARRATIVE**

#### BACKGROUND

On March 29, 1994, Fort Calhoun Station (FCS) received approval (Technical Specification (TS) amendment 162) to revise TS 2.7(1)m that enabled the configuration of the fuel oil system for the emergency diesel generators to meet Institute of Electrical and Electronics Engineers (IEEE) 308, "Standard Criteria for Class 1E Power Systems for Nuclear Power Generating Stations." This provides FCS the capability to provide diesel fuel oil for seven days of diesel generator operation following the most limiting accident condition. The revised TS 2.7(1)m, "Limiting Condition for Operation, Electrical Systems, Applicability, Minimum Requirements (plant greater than 300 degrees F)" states, "One diesel fuel oil storage system containing a minimum volume of 16,000 gallons of diesel fuel in FO-1 and a minimum volume of 10,000 gallons of diesel fuel in FO-10."

The FCS diesel fuel oil system is defined in part as, FO-1, FO-10, FO-37, the credited portable back-up pump, associated piping, other pumps, valves, portable hoses and instrumentation.

The original licensed configuration was to solely use the fuel oil inventory in FO-1, which contains approximately four days supply for the emergency diesel generators. The TS amendment changes included combining the fuel oil inventories of FO-1 and FO-10, "Auxiliary Boiler (AS-1) Fuel Oil Tank" which would extend the operation of the emergency diesel generators to seven days. FO-1 and FO-10 are separate tanks and are not physically connected.

The TS amendment 162 "Discussion, Justification and No Significant Hazards Consideration" section stated that fuel oil make-up to FO-1 could be achieved by manually connecting FO-37 from FO-10 to FO-1 through rubber hose connections. Additionally, a portable pump and hoses were dedicated and stored in an appropriate place as a back-up to FO-37. A preventative maintenance task was developed to periodically verify the pump and hoses are available for use. Since the portable pump is a credited back-up to FO-37, then FO-37 can be out-of-service without violating the TS requirement of having an operable "fuel oil storage system."

FO-37 is a non-Critical Quality Element (CQE) positive displacement pump capable of transferring fuel oil from FO-10 to FO-1, through rubber hose connections, at a rate of 5.8 gpm. The credited portable back-up pump was a non-CQE manual double diaphragm Munster Simms Whale Gusher 30 bilge pump with a nominal rating of 29 gpm.

FCS Procedure EPIP-RR-17A, "TSC Administrative Logistics Coordinator Actions" contains instructions on the use of FO-37 and the portable back-up pump to transfer diesel fuel from FO-10 to FO-1. This procedure also addresses the contingency to have diesel fuel oil delivered via truck from a local vendor. This helps to ensure that there is sufficient diesel fuel oil on site should an accident requiring sustained emergency diesel generator operation.

### **EVENT DESCRIPTION**

On January 6-7, 2010, due to local area flooding FO-37 was rendered inoperable for approximately 24 hours. In response to NRC Resident Inspector questions an engineering review was performed on June 24, 2010, on the capability of the portable back-up pump. This review revealed that the portable back-up pump was not the correct pump for the application and it could not perform its intended function of transferring diesel fuel oil from FO-10 to FO-1 in the event that FO-37 was inoperable. Additionally, on August 30, 2010, the portable back-up pump failed a functional test when the pump diaphragm ruptured.

Since FO-37 was inoperable on January 6-7, 2010, and an engineering evaluation determined the portable back-up pump was not capable of transferring diesel fuel oil from FO-10 to FO-1, then these two components, that are part of the diesel fuel oil system required by TS 2.7(1)m were inoperable concurrently, then this condition is reportable in accordance with 10 CFR 73(a)(2)(i)(B).

NRC FORM 366A (9-2007)

## LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

U.S. NUCLEAR REGULATORY COMMISSION

1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE		
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	2	<b>OF</b> 2
-ort Camoun Station	03000263	2010 -	- 005 -	00	3 <b>U</b> F 3	<b>OF</b> 3

#### **NARRATIVE**

#### CONCLUSION

The root cause is currently under investigation and will be reported in a supplement to this LER.

## **CORRECTIVE ACTIONS**

The non-CQE manual double diaphragm Munster Simms Whale Gusher 30 bilge pump was replaced with a Filterdyne Portable filtration System, Model 757.10.1 and procedure EPIP-RR-17A was revised to address the use of the Filterdyne Portable Filtration System for use as the credited back-up to FO-37. Other actions will be addressed by the FCS corrective action program.

## SAFETY SIGNIFICANCE

The transfer of diesel fuel oil from FO-10 to FO-1 can be accomplished by FO-37, or other portable back-up pumps. FCS procedures also address the delivery of diesel fuel oil on site from a local vendor. Since there are several methods to transfer diesel fuel oil to FO-1, this event has no effect on the health and safety of the public.

## SAFETY SYSTEM FUNCTIONAL FAILURE

This event does not result in a safety system functional failure in accordance with NEI-99-02.

#### PREVIOUS SIMILAR EVENTS

Previous similar events are currently being researched and will be provided in a supplement to this LER.

NRC FORM 366A (9-2007)

PRINTED ON RECYCLED PAPER