

LIC-12-0044 April 23, 2012

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555-0001

Reference: Docket No. 50-285

Subject:

Licensee Event Report 2012-005, Revision 0, for the Fort Calhoun

Station

Please find attached Licensee Event Report 2012-005, Revision 0, dated April 23, 2012. This report is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B), 50.73(a)(2)(ii)(B), 50.73(a)(2)(v)(B) and (D), and 50.73(a)(2)(vii).

No commitments are being made in this letter.

If you should have any questions, please contact me.

Sincerely,

Vice President and CNO

DJB /sds

Attachment

E. E. Collins, Jr., NRC Regional Administrator, Region IV

L. E. Wilkins, NRC Project Manager

J. C. Kirkland, NRC Senior Resident Inspector

INPO Records Center

NRC FOR	RM 366			U.S. NUC	LEAR RE	EGULATO	RY COMMI	ISSION A	PPRO	VED BY OMB: N	NO. 315	0-0104	E	XPIRE	S: 10/	/31/2013	
(10-2010) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)								re lic e: C in aı B cc no	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are inco rporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Priv acy Section (T-5 F53), U.S. Nuclear Regulator y Commission, Washington, DC 205 55-0001, or b y internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sp onsor, and a person is not required to respond to, the information collection.								
1. FACIL	1. FACILITY NAME 2.									2. DOCKET NUMBER 3. PAGE							
			Fort (Calhoun S	Station				05000285 1 OF 3								
4. TITLE TS violation due to inadequate testing of DG fuel pumps																	
5. EVENT DATE 6. LER NUMBER 7. REPORT DATE									8. OTHER FACILITIES INVOLVED								
MONTH DAY YEAR		YEAR	YEAR	SEQUENTI NUMBER		MONTH	DAY	YEAR		CILITY NAME			DOCKET NUMBER 05000 DOCKET NUMBER		00		
02	21	2012		- 005		04	23	2012		LITY NAME					0500	00	
9. OPERATING MODE 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)																	
5							(3)(ii) (4) (i)(A)	□ 50.73(a)(2)(i)(C) □ 50.73(a)(2)(vii) □ 50.73(a)(2)(ii)(A) □ 50.73(a)(2)(viii)(A) □ 50.73(a)(2)(ii)(B) □ 50.73(a)(2)(viii)(B) □ 50.73(a)(2)(iii) □ 50.73(a)(2)(ix)(A)									
10. POW	O	EL	□ 20.2203(a)(2)(ii) □ 50.36(c)(1)(ii)(A) □ 20.2203(a)(2)(iii) □ 50.36(c)(2) □ 20.2203(a)(2)(iv) □ 50.46(a)(3)(ii) □ 20.2203(a)(2)(v) □ 50.73(a)(2)(i)(A) □ 20.2203(a)(2)(vi) □ 50.73(a)(2)(i)(B)				(ii) (i)(A) (i)(B)	□ 50.73(a)(2)(iv)(A) □ 50.73(a)(2)(x) □ 50.73(a)(2)(v)(A) □ 73.71(a)(4) □ 50.73(a)(2)(v)(B) □ 73.71(a)(5) □ 50.73(a)(2)(v)(C) □ OTHER □ 50.73(a)(2)(v)(D) Specify in Abstract below or in NRC Form 366A					elow A				
FACILITY N	AMF				1	2. LICENS	SEE CONT	TACT FOR	R THI	S LER		TELEPHO	NE NUMBER	(Include	Area C	Code)	
					Erick	Matzke							402-53			, , ,	
			13. CON	IPLETE ON				NENT FA	ILUR	E DESCRIBED	IN TH	IS REPO					
CAUSE		SYSTEM		MPONENT	NENT MANU- FACTURER		REPORTABLE TO EPIX		SE	SYSTEM	COMPONENT		MANU- FACTURER		REPORTABLE TO EPIX		
		14.	SUPPLEMENTAL REPORT EXPECTED							15. EXPECTED SUBMISSION			MONTH	DA'	Y	YEAR	
⊠YE\$	S (If yes,	complete	15. EXF	PECTED SU	JBMISSI0	ON DATE)			Ю			V	05	31		12	
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) During a QA review of surveillance procedures, an apparent failure to perform surveillance testing of the full automatic functions of the fuel oil transfer pumps was identified. Technical Specifications require monthly testing of the fuel oil transfer pumps. However, procedure changes made in 1990 removed the test of the automatic start of the fuel oil transfer pumps on low level in the Emergency Diesel Generator (EDG) day tank. Without full testing of the automatic functions of the fuel oil transfer pumps, they cannot be considered operable. Consequently, the EDGs cannot be considered operable because all auxiliary equipment to support operability has not demonstrated that it is fully capable of performing its safety function. There is reasonable assurance that the EDGs and fuel transfer pumps would function as required as the low level switches are calibrated on a refueling frequency and have functioned correctly during extended EDG surveillances. This report is being made in accordance with 10 CFR 50.73(a)(2)(i)(B), 50.73(a)(2)(ii)(B), 50.73(a)(2)(iii), and 50.73(a)(2)(v)(B) and (D). Corrective actions have been developed to revise the Emergency Diesel Generator surveillances to include fuel oil transfer pump surveillance testing.																	

(10 2010)

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

١.	, U.S. NUCLE	AR REGULATORY	COMMISSION
. 1			

1. FACILITY NAME	2. DOCKET	6	. LER NUMBER	3. PAGE			
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	2	OF	3
		2012	- 005 -	0			

NARRATIVE

BACKGROUND

Fort Calhoun Station (FCS) Technical Specifications (TS) require monthly testing of the fuel oil transfer pumps. However, procedure changes made in 1990 removed the test of the automatic start of the fuel oil transfer pumps on low level in the Emergency Diesel Generator (EDG) day tank. Without full testing of the automatic functions of the fuel oil transfer pumps, they cannot be considered operable. Consequently, the EDGs cannot be considered operable because all auxiliary equipment to support operability has not demonstrated that it is fully capable of performing its safety function.

"A system, subsystem, train, component or device shall be OPERABLE or have OPERABILITY when it is capable of performing its specified safety function(s) and when all necessary attendant instrumentation, controls, normal or emergency electrical power sources, cooling and seal water, lubrication, and other auxiliary equipment that are required for the system, subsystem, train, component or device to perform its specified safety function(s) are also capable of performing their related support function(s)."

Monthly fuel oil transfer pump testing is required by TS 3.7(1) e. and Table 3-2, Item 12.

EVENT DESCRIPTION

During a Quality Assurance (QA) review of surveillance procedures, an apparent failure to perform surveillance testing of the full automatic functions of the EDG fuel oil transfer pumps was identified. Technical Specifications require monthly testing of the fuel oil transfer pumps. However, procedure changes made in 1990 removed the test of the automatic start of the fuel oil transfer pumps on low level in the EDG day tank. Without full testing of the automatic functions of the fuel oil transfer pumps, they cannot be considered operable. Consequently, the EDGs cannot be considered operable because all auxiliary equipment to support operability has not demonstrated that it is fully capable of performing its safety function.

CONCLUSION

A cause determination is in progress. The results of the evaluation will be published in a revision to this LER.

CORRECTIVE ACTIONS

Corrective actions have been developed to revise the EDG surveillance tests to include fuel oil transfer pump surveillance testing.

Additional corrective actions may be developed based on the conclusions of the cause analysis.

NRC FORM 366A

(10-2010)

LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6	. LER NUMBER	3. PAGE			
Fort Callbour Station	05000395	YEAR	SEQUENTIAL NUMBER	REV NO.	0	OF	0
Fort Calhoun Station	05000285	2012	- 005 -	0	3		3

NARRATIVE

SAFETY SIGNIFICANCE

Failure to fully test the automatic functions of the fuel oil transfer pumps renders the pumps inoperable. Therefore, consistent with the definition of OPERABLE, the EDGs cannot be considered operable as they rely upon the fuel oil transfer pumps to ensure an adequate fuel supply when the EDGs are performing their safety function. The EDGs have been technically inoperable in excess of TS allowed times. However, there is reasonable assurance that the EDGs and fuel transfer pumps would function as required as the low level switches are calibrated on a refueling frequency and have functioned correctly during extended EDG surveillances.

FCS TS do not contain electrical system requirements for shutdown conditions. The inoperability of the EDGs in the current operating MODE does not violate TS. The EDGs will be fully operable prior to plant restart and modes of applicability.

SAFETY SYSTEM FUNCTIONAL FAILURE

This event does result in a safety system functional failure in accordance with NEI-99-02.

PREVIOUS EVENTS

Previous events will be identified by the cause analysis and included in the supplement to this LER.