

January 19, 2011 LIC-11-0005

U. S. Nuclear Regulatory Commission

Attn: Document Control Desk Washington, DC 20555-0001

Reference: Docket No. 50-285

Subject: Licensee Event Report 2010-005, Revision 1, for the Fort Calhoun

Station

Please find attached Licensee Event Report 2010-005, Revision 1, dated January 19, 2011. This supplemental report is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B).

No regulatory commitments are contained in this submittal. If you should have any questions, please contact me.

Sincerely.

Jeffrey A. Reinhart Sile Vice President

JAR/rda

Attachment

c: E. E. Collins, NRC Regional Administrator, Region IV

L. E. Wilkins, NRC Project Manager

J. C. Kirkland, NRC Senior Resident Inspector

INPO Records Center

TE22 HPR

NRC FORM 366 (9-2007)		U.S. NUCLEAR REGULATORYCOMMISSION						APPROVED BY OMB: NO. 3150-0104 EXPIRES: 08/31/2010										
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)									Estimated burden per response to comply with this mandatory collection request: 80 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.									
1. FACILITY NAME								2. D	OCKET NUM		3. PAGE							
			Fort Calhoun Station						05000285				1 OF 3					
4. TITLE Inoperability of the Emergency Diesel Generator Fuel Oil Transfer System 5. EVENT DATE 6. LER NUMBER 7. REPORT DATE 8. OTHER FACILITIES INVOLVED																		
5. EV	ENT D	ATE		R NUMBER		7. RI	EPORT	DAT										
MONTH	DAY	YEAR	YEAR		REV NO	MONT H	DAY	YE	AR	FACILITY NAME						05000		
1	6	2010	2010	- 005 -	01	1	26	20	11	1 FACILITY NAME					050	00		
9. OPERATING MODE 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)																		
□ 20.2201(b) □ 20.2203(a)(3)(i) □ 50.73(a)(2)(i)(C) □ 50.73(a)(2)(vii)											i)							
	1		☐ 20.2201(d)			□ 20	.2203(a)(3)(ii))		50.73(a)(2)(ii)(A) 🛮 50.7		.73(a)(2)(viii)(A)			
			20.2203(a)(1)			20.2203(a)(4		a)(4)			50.73(a)(2)(ii)(B)			50.73(a)(2)(viii)(B)		ii)(B)		
			□ 20.2203(a)(2)(i)			□ 50.36(c)(1)(i)(A)		50.73	i(a)(2)(iii)		50.73(a)(2)(ix)(A))(A)			
10. POW	ER LE	/EL	20.2203(a)(2)(ii)			☐ 50.36(c)(1)(ii)(A			4)		50.73	i(a)(2)(iv)(A)		50.73(a)(2)(x))		
			☐ 20.2203(a)(2)(iii)			□ 50.36(c)(2)					50.73	(a)(2)(v)(A)		73.71(a)(4)				
	100		20.2		☐ 50.46(a)(3)(ii)				50.73	i(a)(2)(v)(B)		73.	73.71(a)(5)					
			□ 20.2203(a)(2)(v)			□ 50.73(a)(2)(i)(A))		50.73	I(a)(2)(v)(C)		☐ OTHER				
			□ 20.2 2	X 50.73(a)(2)(i)(B))	50.73(a)(2)(v)(D)			Specify in Abstract below or in NRC Form 366A							
					12.	ICENSE	E CON	ITAC	FOF	THIS LER						0007		
FACILITY	NAME		Richard Acker						TELEPHONE NUMBER (include Area Code) 402-533-6561									
			13. COMPLE	TE ONE LIN	E FO	REACH	COMP	ONEN	T FA	ILURE DES	CRIB	ED IN THIS	S REPOR	T		***		
CAUSE			COMPONEN	MASHI		REPORTABLE TO EPIX			JSE	SYSTEM		COMPONENT	MANU- FACTURER		REPORTABLE TO EPIX			
		-			\dagger		\top				\dagger	· · •	 					
Yes (If y	es, co		UPPLEMENTAL REPORT EXPECTED 15. EXPECTED SUBMISSION DATE) NO XX					×		15. EXPECTED SUBMISSION DATE		SION	MONTH		DAY	YEAR		
ABSTRAC	T (Limit	to 1400 sp	aces, i.e., appi	oximately 15 si	ngle-s _l	aced type	written	lines)										
Diesel Fuel Oil Transfer Pump FO-37 and its credited portable back-up pump were inoperable on January 6-7, 2010. On January 6, 2010, FO-37 was rendered inoperable due to local area flooding caused by the rupture of FP-772, "Service Building Fire Sprinkler Isolation Valve". A function of FO-37 is to transfer diesel fuel between "Diesel Fuel Oil Storage Tanks" FO-10 and FO-1. On June 24, 2010, an engineering evaluation determined that the credited portable back up pump to FO-37 was not the correct pump for the application and would not transfer diesel fuel oil from FO-10 to FO-1 as intended. Since both pumps (FO-37 and the credited portable back-up pump) were inoperable this is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B).																		
A root cause analysis determined there was a failure to perform an appropriate design change evaluation for maintaining diesel fuel oil transfer system capability as required by Technical Specification Amendment 162, dated March 29, 1994. The originally credited portable back-up pump was replaced with a new portable pump that has the capability to transfer diesel fuel oil between tanks FO-10 and FO-1. The appropriate procedures were revised to address the pump replacement.																		

NRC FORM 366A LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION CONTINUATION SHEET 1. FACILITY NAME 2. DOCKET 6. LER NUMBER 3. PAGE

1. FACILITY NAME	2. DOCKET	1	6. LER NUMBER			3. PAGE	
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	2	OF 3	0
Fort Camoun Station		2010	- 005 -	- 01		OF 3	

NARRATIVE

BACKGROUND

On March 29, 1994, Fort Calhoun Station (FCS) received approval (Technical Specification (TS) amendment 162) to revise TS 2.7(1)m that enabled the configuration of the fuel oil system for the emergency diesel generators to meet Institute of Electrical and Electronics Engineers (IEEE) 308, "Standard Criteria for Class 1E Power Systems for Nuclear Power Generating Stations." This provides FCS the capability to provide diesel fuel oil for seven days of diesel generator operation following the most limiting accident condition. The revised TS 2.7(1)m, "Limiting Condition for Operation, Electrical Systems, Applicability, Minimum Requirements (plant greater than 300 degrees F)" states, "One diesel fuel oil storage system containing a minimum volume of 16,000 gallons of diesel fuel in FO-1 and a minimum volume of 10,000 gallons of diesel fuel in FO-10."

The FCS diesel fuel oil system is defined in part as, FO-1, FO-10, FO-37, the credited portable back-up pump, associated piping, other pumps, valves, portable hoses and instrumentation.

The original licensed configuration was to solely use the fuel oil inventory in FO-1, which contains approximately four days supply for the emergency diesel generators. The TS amendment changes included combining the fuel oil inventories of FO-1 and FO-10, "Auxiliary Boiler (AS-1) Fuel Oil Tank" which would extend the operation of the emergency diesel generators to seven days. FO-1 and FO-10 are separate tanks and are not physically connected.

The TS amendment 162 "Discussion, Justification and No Significant Hazards Consideration" section stated that fuel oil make-up to FO-1 could be achieved by manually connecting FO-37 from FO-10 to FO-1 through rubber hose connections. Additionally, a portable pump and hoses were dedicated and stored in an appropriate place as a back-up to FO-37. A preventative maintenance task was developed to periodically verify the pump and hoses are available for use. Since the portable pump is a credited back-up to FO-37, then FO-37 can be out-of-service without violating the TS requirement of having an operable "fuel oil storage system."

FO-37 is a non-Critical Quality Element (CQE) positive displacement pump capable of transferring fuel oil from FO-10 to FO-1, through rubber hose connections, at a rate of 5.8 gpm. The credited portable back-up pump was a non-CQE manual double diaphragm Munster Simms Whale Gusher 30 bilge pump with a nominal rating of 29 gpm.

FCS Procedure EPIP-RR-17A, "TSC Administrative Logistics Coordinator Actions" contains instructions on the use of FO-37 and the portable back-up pump to transfer diesel fuel from FO-10 to FO-1. This procedure also addresses the contingency to have diesel fuel oil delivered via truck from a local vendor. This helps to ensure that there is sufficient diesel fuel oil on site should an accident requiring sustained emergency diesel generator operation.

EVENT DESCRIPTION

On January 6-7, 2010, due to local area flooding FO-37 was rendered inoperable for approximately 24 hours. In response to NRC Resident Inspector questions an engineering review was performed on June 24, 2010, on the capability of the portable back-up pump. This review revealed that the portable back-up pump was not the correct pump for the application and it could not perform the function of transferring diesel fuel oil from FO-10 to FO-1 in the event that FO-37 was inoperable. Additionally, on August 30, 2010, the portable back-up pump failed a functional test when the pump diaphragm ruptured.

Since FO-37 was inoperable on January 6-7, 2010, and an engineering evaluation determined the portable back-up pump was not capable of transferring diesel fuel oil from FO-10 to FO-1, then these two components, that are part of the diesel fuel oil system required by TS 2.7(1) m were inoperable concurrently, then this condition is reportable in accordance with 10 CFR 73(a)(2)(i)(B).

NRC FORM 366A (9-2007)	CONTINU		U.S. NI	S. NUCLEAR REGULATORY COMMISSION				
1. FACILITY NAME	2. DOCKET		6. LER NUMBER			3. P	AGE	
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	,	OF	3	
Fort Cambuil Station	05000205	2010 -	005 -	01	3		J	

NARRATIVE

CONCLUSION

The root cause was determined to be the failure to perform an appropriate design change evaluation for maintaining diesel fuel oil transfer system capability which was required by Technical Specification Amendment 162, dated March 29, 1994.

CORRECTIVE ACTIONS

The non-CQE manual double diaphragm Munster Simms Whale Gusher 30 bilge pump was replaced with a Filterdyne Portable filtration System, Model 757.10.1. Procedure EPIP-RR-17A was revised to address the use of the Filterdyne Portable Filtration System for use as the credited back-up to FO-37. Other actions will be addressed by the FCS corrective action program.

SAFETY SIGNIFICANCE

The transfer of diesel fuel oil from FO-10 to FO-1 can be accomplished by FO-37, or other portable back-up pumps. FCS procedures also address the delivery of diesel fuel oil on site from a local vendor. Since there are several methods to transfer diesel fuel oil to FO-1, this event has no effect on the health and safety of the public.

SAFETY SYSTEM FUNCTIONAL FAILURE

This event does not result in a safety system functional failure in accordance with NEI-99-02.

PREVIOUS SIMILAR EVENTS

None

NRC FORM 366A (9-2007) PRINTED ON RECYCLED PAPER