

NATIONAL SENIOR CERTIFICATE EXAMINATION NOVEMBER 2022

NAUTICAL SCIENCE: PAPER I

MARKING GUIDELINES

Time: 3 hours 150 marks


These marking guidelines are prepared for use by examiners and sub-examiners, all of whom are required to attend a standardisation meeting to ensure that the guidelines are consistently interpreted and applied in the marking of candidates' scripts.


The IEB will not enter into any discussions or correspondence about any marking guidelines. It is acknowledged that there may be different views about some matters of emphasis or detail in the guidelines. It is also recognised that, without the benefit of attendance at a standardisation meeting, there may be different interpretations of the application of the marking guidelines.


SECTION A: PRACTICAL CHARTWORK

QUESTION 1


1.1	True course to counter current Leeway Course to steer	326° (T) 5° – 321° (T) Chart
1.2	Set & drift	085º × 0,8' Chart
1.3	New course required at 10:30 Course to allow for set & drift	339º (T) 333º (T) Chart







2.1 Chart work




		CHARI
Course to make Whittle Rock abeam	=	343° (T)
True course to steer to counter current	=	356° (T)
Variation	=	22° W
Magnetic course	=	018° (M)
Deviation	=	4º E
Compass course to steer	=	014° (C)

2.2 Distance over ground in $\frac{1}{2}$ = 5,1'
Speed over ground = 10,2 knots
Distance to Whittle Rock abeam = 15,3 M
@ 12,4 kts = $1^h 30^m$ ETA Whittle Rock abeam = 14:30


- 3.1 20:30 Position on the chart SSE of "East Shoal".
- 3.2 The two immediate hazards are "East Shoal" and "York Shoal". The vessel must keep at least ½ mile south of these two hazards.
 - From the 20:30 position the vessel is in danger of being close to "East Shoal" and hitting "York Shoal". The Navigator should therefore alter course to the South.
- 3.3 As indicated on the chart immediately adjust course to the south to 261° (T). Thereafter when York Shoal has been cleared to the south alter course to 271° (T) to make for the anchorage position in Simon's Bay.

Chart



4.1	Draught UKC Required depth Shoal depth Required height of tide	2,8 m 1,0 m 3,8 m 2,5 m 1,3 m
	am Tides 25 November Depth 01:00 Depth 02:00 Depth Diff over 60 minutes	1,25 m 1,61 m 0,36 m
	Time Diff 0,05 x 60 / 0,36 Required 1,3 m will be at	8 min 01:08


4.2



4.3 The range of the tide on 25 November was from 1,81–0,25 m; or 1,56 m.

The duration of the tide is from 03:22 to 09:26 or 6hrs 4mins.

5.1 On the chart



- Reporting points for the Inshore Traffic Zone are: "4" on departure Port of Cape Town; 5.2

 - "1D" at the termination of the Traffic Zone;
 - "B" entering Houtbaai.
- SAN 1015 as marked at the end of the Inshore Traffic Zone. 5.3

SECTION B: ASTRO-NAVIGATION

QUESTION 6

LMT mer passage Longitude 017° 56 GMT mer pass Zone (+2)		(-)
Dec. 10:00 'd' (38') Dec 10:38	21° 56,8′ 0,2′ 21° 57,0′	(+)
Sextant alt. Index error Observed alt. Dip Apparent alt. Total correction True alt.	77° 56,2' 1,0' 77° 57,2' 6,1' 77° 51,1' 16,0' 78° 07,1' 90° 00,0'	(-)
	•	

Vessel course due south, therefore Longitude remains same as at the star position at 05:30.

Vessel position at meridian passage was 33° 50' S 017° 50' E

7.1	LMT Sunset Lat 32° S Longitude 016° 50' E GMT sunset Zone (–2) Zone time	18:52 01:07 17:45 01:00 18:45	. ,
7.2	Decl. 17:00 'd' 0,4 Decl. 17:45	21º 50,4' 0,3' 21º 50,7'	(+)
	Sin Amp. = Sin Dec/Cos Lat Amplitude	Sin 21º 50,7'/Cos32º	= 0,4387687 = W26°N
	True bearing Compass bearing Compass error	296° 323° 27°	w
7.3	Variation Deviation	22° 5°	W W
7.4	Ship's head Deviation Magnetic heading Variation Ship's heading	234° 5° 229° 22° 207°	E (M) W

Total: 150 marks