



Darshan Singh

License No. SLA-85348
VPO. Dala, Patti Jagga
Near Power House, Moga.
GSTIN 03BUAPG1554L1ZX

Valid Upto – 05/03/2029
darshangill5@gmail.com
Phone No. 01636-512872
Mobile No. 95175-76989

Surveyor & Loss Assessor IIISLA M/NO. : A/N/09330

MOTOR SURVEY REPORT SPOT

This report is issued without prejudice, in respect of cause, nature and extent of loss / damage & subject to the terms & conditions of insurance policy upon which the claim has been made.

Ref. No. UIIC/2025/067

26/03/2026

1. INSURANCE PARTICULARS

- A. POLICY NO. : 2013063125P111921386
- B. PERIOD OF INSURANCE : 25.10.2025 to 24.10.2026
- C. SUM INSURED : 09,00,000 /-
- D. INSURER : UNITED INDIA INSURANCE CO. LTD.
B.O., NAKODAR (PB).
- E. INSURED : M/s. New Fargo Trading Company, R/o Focal Pont, Moga,
Distt. Moga. (97814-51212)

2. VEHICLE PARTICULARS Form 24 As produced Verified & Found in Order

- a] Registration No. : **PB 04AB 1297**
- b] Date of registration : 26-12-2018
- c] Engine No. : E414CDJK242218 | **PHYSICALLY VERIFIED**
- d] Chassis No. : MC2B7ERC0JK420404 |
- e] Make /Model : **VE COMMERCIAL / EIHER PRO 1059XP E HSD / 10.2018**
- f] Type of Body : HIGH SIDE DECK
- g] Class of vehicle (use) : GOODS CARRIER (LGV)
- h] Pre accident condition : GOOD
- i] Registration Laden weight : 7200 KG
- j] Unladen weight : 2875 KG
- k] Fitness valid up to : 20-02-2026



Darshan Singh

License No. SLA-85348
VPO. Dala, Patti Jagga
Near Power House, Moga.
GSTIN 03BUAPG1554L1ZX

Valid Upto – 05/03/2029
darshangill5@gmail.com
Phone No. 01636-512872
Mobile No. 95175-76989

Surveyor & Loss Assessor IIISLA M/NO. : A/N/09330

l]	Carrying capacity	:	4325 KG
m]	Token taxes paid up to	:	To be checked
n]	Market value of the vehicle	:	09,00,000 /.
F.	Regd. Owner	:	M/s. New Fargo Trading Company

3. DRIVER'S PARTICULARS D.L As produced Verified & Found in Order

a]	Name of Driver	:	Mr. Pawan Kumar Arora, S/o Sh. Jagdish Lal
b]	Motor Driving Licence No.	:	PB 2920110005563
c]	Date of issue	:	30-07-2024
d]	Valid Up to	:	02-01-2026 (Trans.), 20-11-2031 (NT)
e]	Issuing Authority	:	L.A., Faridkot
f]	Type of License	:	TRANS., LMV. ONLY

4. ROUTE PERMIT Route Permit As not Produced

a]	Route Permit no.	:	---
b]	Type of permit	:	---
c]	Valid up to	:	---
d]	Area of operation	:	---

5. POLICE REPORT : NOT LODGED

6. DETAIL OF LOAD CHALLAN

The vehicle was empty the time of spot survey.



Darshan Singh

License No. SLA-85348
VPO. Dala, Patti Jagga
Near Power House, Moga.
GSTIN 03BUAPG1554L1ZX

Valid Upto – 05/03/2029
darshangill5@gmail.com
Phone No. 01636-512872
Mobile No. 95175-76989

Surveyor & Loss Assessor IIISLA M/NO. : A/N/09330

-
7. DATE & TIME OF ACCIDENT : 27.11.2025 at about 07:15 AM
- a] Place of accident : AT/Near. Moga, Moga to Ludhiana Road.
- b] Place of workshop/survey : AT SITE
- c] Date of Appointment : **27.11.2025 on telephonic for spot**
- d] Date of Survey : 27.11.2025
-

8. WAS ANY THIRD PARTY : No third party loss was explained to the undersigned.
INVOLVED IN THE ACCIDENT
-

CAUSE & NATURE OF ACCIDENT : As stated by insured form that, near by the place of accident. The insured vehicle was proceeding on its route when the trailer truck moving ahead suddenly applied brakes. The driver of the insured vehicle also applied brakes immediately; however, due to insufficient safe distance, he could not control the vehicle in time and consequently collided with the rear side of the ahead-going trailer truck. The loss occurred accidentally.

THE CAUSE OF ACCIDENT IS ACCIDENTAL IN NATURE AND ALL THE DAMAGES ARE ATTRIBUTED TO IT.

ANY OTHER COMMENTS : – At the time of spot survey no documents like as road tax and permit were not produced by the insured vehicle driver.

Every possible care has been taken in making the spot survey report, besides of these damages if there is any internal/indirect damaged, that may be looked into at the time of final survey in relevance to the history, type & nature of accident.

Insured was advised to contact again insurance company office for final survey before dismantling the vehicle.

Snaps of the damaged vehicle along with survey fee bill are enclosed for favor of your kind approval please.



Darshan Singh

License No. SLA-85348
VPO. Dala, Patti Jagga
Near Power House, Moga.
GSTIN 03BUAPG1554L1ZX

Valid Upto – 05/03/2029
darshangill5@gmail.com
Phone No. 01636-512872
Mobile No. 95175-76989

Surveyor & Loss Assessor IISLA M/NO. : A/N/09330

SURVEY & OBSERVATION

In accordance with the instruction received from your office dated 27.11.2025, undersigned visited the place of accident on 27.11.2025 to inspect the damages to the insured vehicle. The said vehicle was lying there in as its position. Undersigned arranged few photographs of the said vehicle [enclosed]. On inspection undersigned found that the damages to the insured vehicle are to be fresh and further to it as per impact of accident. The cause of accident was also discussed with the insured. Undersigned has physically verified the engine no. & chassis no. of the insured vehicle at the time of spot survey. Undersigned has also physically noted down the damages of the insured vehicle which are produced as below:-

- Front bumper found damaged/dented and misaligned
- Front grille shell found damaged/dented and misaligned
- Cabin found damaged/dented and misaligned
- Dashboard found damaged/broken
- Front windshield glass found damaged
- Front door (LH) found damaged/dented and misaligned
- Footrest (LH) found damaged/dented and misaligned
- Side rear view mirror (LH) found damaged/broken
- Front cabin mounting (LH) found damaged/broken
- Load body (LH) found damaged/dented and misaligned
- Suspension system – to be checked during garage/final survey

Though every care has been taken while noting down the damages but if any damages remained un-noticed, same might be allowed according to cause and nature of accident.

THANKING YOU

ENCL. a/a

CONCLUDED
DARSHAN SINGH





Darshan Singh

License No. SLA-85348
VPO. Dala, Patti Jagga
Near Power House, Moga.
GSTIN 03BUAPG1554L1ZX

Valid Upto – 05/03/2029
darshangill5@gmail.com
Phone No. 01636-512872
Mobile No. 95175-76989

Surveyor & Loss Assessor IIISLA M/NO. : A/N/09330

(Spot Fee Bill)

BILL No. 560

Ref. No. UIIC/2025/067

Date:- 27/03/2026

United India Insurance Co. Ltd.,
GSTIN :- 03AAACU5552C1ZT

SUBJECT:-

Insured's Name	:-	M/s. New Fargo Trading Company
Survey of Vehicle Regd No	:-	PB-04AB-1297
Policy Number	:-	2013063125P111921386
Date of Accident & Time	:-	27-11-2025 at about 07:15am
Date of Survey	:-	27-11-2025

PARTICULARS	AMOUNT
Survey Fee	1000.00
Conveyance	500.00
Digital Photographs @10/-	00.00
	1500.00
Add CGST @09%	135.00
Add SGST @09%	135.00
TOTAL	1770.00

(One Thousand Seven Hundred & Seventy Rs. Only)

BANK OF INDIA
A/C No. 654410110005572
IFSC Code: BKID0006544
Dala Distt. Moga



(Darshan Singh)