## T4 prob 9

Program used	UP2
Materiel used	Used circle alignment fixture and weight
	Used real mems and UPI tube
Result for vacuum	passed
Result for over pressure	failed
Reason for failure	Possibly because of the intentional scratches on the mems
date	10/11/2023
operator	Jaikob williams
Investigate by	Mustafa and jaikob
notes	Mike scratched the mems using a q tip