T3 Prob 3

Program used	Upi updated Step 11 was updated from 325c to 335c
	Step 12 was updated from 1 min to 3mins
Materiel used	Used circle alignment fixture and weight Used dummy mems and ISS tube
Result for vacuum	passed
Result for over pressure	leaked
Reason for failure	tube could have been contaminated
date	9/27/2023
operator	Jaikob williams
Investigate by	Jaikob and nader and mike

