T4 Prob 1

Program used	UPI 2 (Upi2) shares the same settings as (UPI1) with the exception of gas 2 is switched to gas 1 for (UPI2)
Materiel used	Used circle alignment fixture and weight Used real mems and UPI tube
Result for vacuum	leaked
Result for over pressure	n/a
Reason for failure	
date	10/4/2023
operator	Jaikob williams
Investigate by	

