

Serial #: 4200003

By #: Jon Grimm

Customer Service Order

Warranty

#:1029

Shipped:

Warranty: No Status: Closed

Valid Complaint: Yes

Date:

#4200 CRYOTherm Dual Console

Customer (Ship To)

Customer#: 20287

Rogers State University

Trey Robertson

1701 West Will Rogers Blvd.

Claremore, OK 74017

W: (918) 343-5203

C:

H: (918) 346-3576

Customer Description

Patient Injury: No

Pump Control circuit board left pump not working

Received Accessories

Failure Investigation

Invoice #:

Onsite Hrs.

Travel Hrs.

Factory Hrs.

Miles

Per Diem

Service Reports

Date 07/17/2012

Type Field Service

By

Tammy Williamson

Repairs Made

Sent replacement board **Comment**

^

To Spec? No

Warranty Materials

QuantityStock#Description1201003Pump Control Board 20 Min.

Price 22.09

Unit Each Amount 22.09

Total Material Cost: Shipping Cost:

\$22.09 \$35.30

Total:

\$57.39

Materials Received

Quantity

Stock#

Description

201003

Pump Control Board 20 Min.

Action

Date Type

Description

Investigations

Date

Type Description

07/01/2015 Pump control air actuated switch failure (after 2009)