Volture

volture

started 2 minutes 13 seconds ago

Volture

Volture house power	NA
Volture grid voltage	NA
Volture amps	0 A
Volture decision	no_reading_idle
Volture event	dry_run

Volture settings

Volture control	
Volture Shelly EM URL	http://localhost:8081
Volture Grafana push	

Volture diagnostics

Volture Grafana push status	
Volture heap free	81404 B
Volture heap largest block	51200 B
Volture heap min free	59016 B

Sensor and Control

Asleep	
Battery	57 %
Cabin Overheat Protection	On
Cabin Overheat Temperature	High

Cancel Software Update			PRESS
Car Max Acceptable			32 A
Charge Limit Reason			Unknown
Charge Port Door	↑	□	↓
Charge Port Latch	🔒	🔓	↑
Charger			
Charger			
Charger Current			6 A
Charger Max			32 A
Charger Phases			1
Charger Power			1 kW
Charger Power Estimated			1.38 kW
Charger Voltage			230 V
Charging			Stopped
Charging Amps	0	10	32 A
Charging Limit	50	94	100 %
Charging Rate			0.0 mph
Climate	Current: 22.0 °C Target: 15	22.0	28
	Mode: HEAT_COOL		
Doors	🔒	🔓	↑
Energy Added			0.5 kWh
Flash Lights			PRESS
Front Left Seat Climate	Off		
Front Right Seat Climate	Off		

Frunk	↑ □ ↓
Heated Steering	
Install Software Update	PRESS
Outside Temperature	26.5 °C
Parking Brake	
Range	139 mi
Rear Left Seat Heat	Off
Rear Right Seat Heat	Off
Sentry Mode	
Software Update	Downloading
Sound Horn	PRESS
Time to Full	580 min
TPMS Front Left	2.5 bar
TPMS Front Right	1.8 bar
TPMS Rear Left	2.5 bar
TPMS Rear Right	2.4 bar
Trunk	↑ □ ↓
User Present	
Wake up	PRESS
Windows	↑ □ ↓

Diagnostic

BLE Connection	
BLE Signal	-26 dBm
Force data update	PRESS
IP Address	192.168.0.113

Pair BLE Key	PRESS
Pairing Required	○
Restart	PRESS
Software Update Version	2026.38.3.1
Status	○
Steering Heat Mode	Off
Uptime	122 s
Version	2026.9.1 (config hash 0xc14850ca, built 2026-10-16 00:28:51 +0200)
WiFi Signal	-72 dBm

SHOW ALL

Debug Log

```
Time     Tag          Message
00:31:41 [component… http_request set Error flag: unspecified
00:31:41 [http_requ… HTTP Request failed: ESP_ERR_HTTP_CONNECT
00:31:41 [volture:2… volture
                     power_w=-1,valid=0,car_charging=0,car_amps=10,amps=0,cont…
00:31:42 [component… http_request cleared Error flag
00:31:46 [ble_rssi_… ESP_GAP_BLE_READ_RSSI_COMPLETE_EVT RSSI: -26
00:31:46 [esp-       E (122564) esp-tls: [sock=55] delayed connect error:
         idf:000]    Connection reset by peer
00:31:46 [esp-       E (122568) transport_base: Failed to open a new
         idf:000]    connection: 32772
00:31:46 [esp-       E (122569) HTTP_CLIENT: Connection failed, sock < 0
         idf:000]
00:31:46 [component… http_request set Error flag: unspecified
00:31:46 [http_requ… HTTP Request failed: ESP_ERR_HTTP_CONNECT
00:31:46 [volture:2… volture
                     power_w=-1,valid=0,car_charging=0,car_amps=10,amps=0,cont…
00:31:47 [tesla_ble… Polling VCSEC
00:31:47 [component… http_request cleared Error flag
00:31:47 [TeslaBLE:  ehicle:628]: [VCSEC Poll] Command completed successfully
                     in 166 ms
00:31:51 [esp-       E (127564) esp-tls: [sock=55] delayed connect error:
         idf:000]    Connection reset by peer
00:31:51 [esp-       E (127569) transport_base: Failed to open a new
         idf:000]    connection: 32772
00:31:51 [esp-       E (127571) HTTP_CLIENT: Connection failed, sock < 0
         idf:000]
00:31:51 [component… http_request set Error flag: unspecified
00:31:51 [http_requ… HTTP Request failed: ESP_ERR_HTTP_CONNECT
```

```
00:31:51 [volture:2… volture
                     power_w=-1,valid=0,car_charging=0,car_amps=10,amps=0,cont…
00:31:52 [component… http_request cleared Error flag
00:31:56 [esp-       E (132564) esp-tls: [sock=55] delayed connect error:
         idf:000]    Connection reset by peer
00:31:56 [esp-       E (132570) transport_base: Failed to open a new
         idf:000]    connection: 32772
00:31:56 [esp-       E (132572) HTTP_CLIENT: Connection failed, sock < 0
         idf:000]
00:31:56 [component… http_request set Error flag: unspecified
00:31:56 [http_requ… HTTP Request failed: ESP_ERR_HTTP_CONNECT
00:31:56 [volture:2… volture
                     power_w=-1,valid=0,car_charging=0,car_amps=10,amps=0,cont…
00:31:57 [tesla_ble… Polling VCSEC
00:31:57 [tesla_ble… Polling Infotainment (active - WAKE_IF_NEEDED)
00:31:57 [TeslaBLE:  ehicle:628]: [VCSEC Poll] Command completed successfully
                     in 131 ms
00:31:57 [component… http_request cleared Error flag
00:31:57 [TeslaBLE:  ehicle:628]: [Charge State Poll] Command completed
                     successfully in 451 ms
00:31:58 [TeslaBLE:  ehicle:628]: [Climate State Poll] Command completed
                     successfully in 338 ms
00:31:58 [TeslaBLE:  ehicle:628]: [Drive State Poll] Command completed
                     successfully in 429 ms
00:31:59 [TeslaBLE:  ehicle:628]: [Closures State Poll] Command completed
                     successfully in 334 ms
00:31:59 [TeslaBLE:  ehicle:628]: [Tire Pressure Poll] Command completed
                     successfully in 358 ms
00:31:59 [TeslaBLE:  ehicle:628]: [Software Update Poll] Command completed
                     successfully in 318 ms
00:32:01 [esp-       E (137564) esp-tls: [sock=55] delayed connect error:
         idf:000]    Connection reset by peer
00:32:01 [esp-       E (137570) transport_base: Failed to open a new
         idf:000]    connection: 32772
00:32:01 [esp-       E (137573) HTTP_CLIENT: Connection failed, sock < 0
         idf:000]
00:32:01 [component… http_request set Error flag: unspecified
00:32:01 [http_requ… HTTP Request failed: ESP_ERR_HTTP_CONNECT
00:32:01 [volture:2… volture
                     power_w=-1,valid=0,car_charging=0,car_amps=10,amps=0,cont…
00:32:02 [component… http_request cleared Error flag
00:32:06 [esp-       E (142564) esp-tls: [sock=55] delayed connect error:
         idf:000]    Connection reset by peer
00:32:06 [esp-       E (142572) transport_base: Failed to open a new
         idf:000]    connection: 32772
00:32:06 [esp-       E (142575) HTTP_CLIENT: Connection failed, sock < 0
         idf:000]
00:32:06 [component… http_request set Error flag: unspecified
00:32:06 [http_requ… HTTP Request failed: ESP_ERR_HTTP_CONNECT
00:32:06 [volture:2… volture
                     power_w=-1,valid=0,car_charging=0,car_amps=10,amps=0,cont…
```