NPORS – Slinger Signaller Experienced Worker Assessment

Number of Delegates: 1 – 6 Course Duration: 1 Day

Course Outcome: NPORS ID Card / Certificate

Construct on Skils People Gualifications & Training A Skills People Group Company

COURSE PROGRAMME

The NPORS - Slinger Signaller Experienced Worker Assessment course assesses the delegates on the following:

- Current relevant legislation
- Provision and use of work regulation
- Understanding the roles of a slinger signaller
- Pre-use inspections
- · All instruments and controls
- Slinging angles and techniques
- Load movement and effect to lifting equipment
- Calculating safe working loads
- Signals
- Handling loads of various weights and dimensions

01246 589444
info@skillspeoplegroup.com
ConstructionSkillsPeople.com

Introduction

This course is designed for experienced operatives to prove their competence in safely and efficiently operating a slinger signaller to the occupational standards as laid down by the awarding organisation, NPORS.

Aims & Objectives

To test and assess the competency of a slinger signaller operator against a testing specification aligned to the national occupational standards. The delegate will undergo both a theory and practical test.

Course Delivery

This course is delivered using a mixture of both classroom-based tutorials and practical machine operating, testing and a final course assessment paper.

Location

This course can be delivered on site or at a location suitable to you.

Certification

Successful delegates will qualify for a NPORS photo ID card and certificate of competence valid for 3 years.

Delegate Eligibility/Entry Requirements

It is important that all delegates have a good understanding of spoken and written English.

Additional Information

Delegates should be physically fit and inform the trainer if they are taking any medication that may affect their ability to operate machinery. Delegates will need to provide a passport photograph on the day of training and wear appropriate PPE.















