

3. Design & Optimize


⇔ Status	Completed
⊿ Sub-	3.1 Define Constraints, 4 3.2 Sketches, 4 3.3 Design
task	Decision Matrix

3.1 Define Constraints

- Take-up ≥10mm
- Latch style = Under Center
- Mounting
 - Style = Surface Mount
 - Screw size = M3
- Overall
 - Length ≥40mm
 - o Width ≥20mm
- Projection ≤13mm

3.2 Sketches

3. Design & Optimize



3. Design & Optimize