

Risk Assessment

Title	Working at Height and underground	Date of Assessment	Invalid date
Site	Heathway Avenue LN41UJ	Locaiton	Heathway Avenue LN41UJ
Risk Assessor	Anayat Abdul Aziz	Assissted By	-
Non-Employees Involved	-	People at Risk	Employees, Member of the public, Visitors, Contractors
Task Description	To Conduct Risk Assessment at Height and Underground		
Risk Rating			
Review Date	-	Reviewer	

<u>Hazards</u>

Risk of Harm

Existing Control

Measures

Vehicle accident

Starting Point (IDS)

Hazard	Work at height
Risk of Harm	Falls from height when using ladders and steps
Existing Control Measures	- Correct manual handling techniques as per ladder training Correct PPE inc. safety helmet - Equipment maintenance procedures No climbing during adverse weather conditions
Hazard	Road risk

- Sign on duty of care system. - Route planning. - Phone ahead, ask for dogs to

(location dependant) - Defensive driving techniques applied (as per training). -

be put away prior to arrival and ask about onsite hazards if appropriate

Hazard	Work equipment	
Risk of Harm	Injuries inside the vehicle (taking material)	
Existing Control Measures	- Assessment of manual handling tasks (TILE) Training in correct kinetic lifting techniques Use of mechanical aids, e.g. swing lift crane where appropriate Correct loading of vehicle as per vehicle layout diagrams Keeping the work area clear -	
Hazard	Manual handling	
Risk of Harm	Injuries with lids	
Existing Control Measures	- Maintaining clear and guarded work area Use of Manhole Cover Lifter 4A or Key - Joint Box No. 5 with roller bar in-line with the training given Correct use of the 2/4 head Gas - Detection Unit as per training given Manager Supervisory checks	
Hazard	Wind, rain, snow and ice	
Risk of Harm	Slips, falls and road accidents	
Existing Control Measures	- Prevent workers from draughts - Provide PPE, such as insulated jackets, trousers, safety boots, baclavas etc Provide frequent breaks and job rotations - Provide warm drinks and food - Avoid working below 0° C - Avoid working on ladders at high speed	
Hazard	Gas Appliances and Equipment	
Risk of Harm	Intoxication with flammable gas	
Existing Control Measures	- Pre-work gas test checks using Gas - Detection Unit (GDU) and on-going use as a sentinel Venting structure using a forced air blower (applicable to specific circumstances as directed by training) - Confined space working with BA equipment (applicable	
Hazard	Confined Spaces	
Risk of Harm	Inability to scape the area	
Existing Control Measures	- Assessment of work area in line with policies and provided training Full Confined Spaces Control Measures (as required) De-classified control measures (inc. forced air blower, 2 person working and ability to affect an escape easily in an emergency	

Hazard	Hazardous Substances
Risk of Harm	Intoxication with toxic water
Existing Control Measures	- Pre-work gas test checks using Gas Detection Unit (GDU) and on-going use as a sentinel Venting structure using a forced air blower (applicable to specific circumstances as directed by training) - Confined space working with BA equipment (applicable to specific - circumstances as directed by training)
Hazard	Fire
Risk of Harm	Fire on site or nearby
Existing Control Measures	- Follow the training provided - Identify the type of fire - Fire triangle (Oxigen, Heat and Fuel) - Correct use of a gas extinguisher - If is uncontrollable, call a fireman

Reviews