# **Construction Daily**

### 1995 Highway 65, Wheatland, Ca. 95692

| 530-652-4169 | WALKER<br>TELECOMM, INC. |  |
|--------------|--------------------------|--|
|              | TELECUTIFI, INC.         |  |

### **Daily Construction Report**

| Project Name | Amazon warehouse stockton |
|--------------|---------------------------|
| Job Number   | 6087                      |
| Report By    | Andrew Lucero             |
| Date         | 06/16/2021                |

#### Weather

| Notes                     |  |
|---------------------------|--|
| <b>Current Conditions</b> |  |

#### Remarks

| Describe Work Accomplished          | Mark asked us to put the doors on to the turnstiles. I was going to leave them off until the concrete grinders were done to avoid damage, but he said they would protect them. So we installed them.  Dumped all cardboard and other trash from turnstiles.  Installed all 3 panels for ACP 8, Installed ACP 9 and ACP 10  Dropped cables for ACP 2 and 3. |
|-------------------------------------|--|
| Materials and Equipment On Site     |  |
| Special Instructions of Contractors |  |

## **Exceptions or Defects**

| Specification Number               |  |
|------------------------------------|--|
| Drawing Number                     |  |
| Location                           |  |
| Description of Exception or Defect |  |

### **Foreman Comments**

| Actual Percentage of Work Completed |                               |
|-------------------------------------|-------------------------------|
| Projected Completion Date           |                               |
| <b>Total Crew Hours Worked</b>      |                               |
| List of Employees On Site           | Andrew Miguel Bryan Ryan Linn |

# **Construction Daily**

| Additional Comments        | I'm noticing some of the scheduled devices for the field might not work for the application they are saying. The schedule shows us putting the same style horn outside on the guard shack, the same style 360 motions as the warehouse in the guard shack and in office spaces. And the REX motions being the same as the standard motion. And a majority of the door contacts we were given won't work with some doors on site. We might need to get this ironed out.  Also still need the LNL-1100 board for the guard shack, 360 motions, 2000' reels of cable for the backbone tie cable. |
|----------------------------|---|
| Attachments Sent Via Email | No  |
| Foreman Signature          | andle   |
| Today's Date               | 06/16/2021  |