Inspection summary

Property	412 Linden Ct · single-family, 2 stories, built 1987, about 2,140 sq ft
Client	Jen and Tom Park (buyers)
Inspected	Saturday, October 11, 2026 · 9:00 am to 12:30 pm · weather clear, 61°F
Inspector	Bay Area Inspections · license on file · sample report

This report records the condition of the visible, accessible parts of the home on the day of inspection. Items are rated Satisfactory, Monitor or Repair. Repair items are listed with a recommendation; the inspector does not estimate costs.

Summary of findings

• Repair · Rear deck guardrail (page 4)

• Repair · GFCI protection missing at one exterior outlet (page 9)

• Monitor · Minor efflorescence on north foundation wall (page 6)

• Monitor · Water heater is 11 years old (page 14)

• Satisfactory · Roof covering, about 6 years old (page 3)

• Satisfactory · Furnace, serviced March 2026 (page 12)

Roof and gutters

Roof covering · Satisfactory. Architectural asphalt shingles, about 6 years old. No missing or lifted shingles observed. Flashing at the chimney is sealed.

Gutters and downspouts · Satisfactory. Gutters are clear. Downspouts discharge at least 4 feet from the foundation.

Exterior: decks, balconies and railings

Rear deck structure · Satisfactory. Pressure-treated framing on concrete footings. Ledger is flashed and bolted to the house. No soft or decayed boards found.

Rear deck guardrail · Repair. Rear deck guardrail is loose at two posts and does not meet height requirements. Recommend repair by a qualified contractor prior to closing. Measured guard height is about 32 inches; current guidance for decks is at least 36 inches.

Front porch steps · Satisfactory. Handrail is secure. Riser heights are even.

Exterior: siding, windows and doors

Siding · Satisfactory. Fiber-cement lap siding in good condition. Caulk at window trim is intact.

Windows · Satisfactory. Double-pane vinyl windows open and lock. No failed seals observed.

Exterior doors · Satisfactory. Weatherstripping is intact at the front and rear doors.

Foundation and grading

Foundation walls · Monitor. Minor efflorescence on the north foundation wall, about 3 feet wide. No active moisture at the time of inspection. Keep gutters clear and recheck after heavy rain.

Grading · Satisfactory. Soil slopes away from the house on all sides.

Photo index

Photos for the sections above are kept in the online copy of this report.

Garage

Garage door and opener · Satisfactory. Auto-reverse works when the door meets resistance. Photo-eyes are mounted at the correct height.

Fire separation door · Satisfactory. Solid-core door between the garage and the house closes and latches.

Electrical: service and panel

Service panel · Satisfactory. 200 amp panel in the garage. Breakers are labeled. No double-tapped breakers.

Exterior outlets · Repair. GFCI protection is missing at the exterior outlet by the rear deck. Recommend a licensed electrician install GFCI protection.

Attic and insulation

Attic access · Satisfactory. Pull-down stair in the hall closet. Hardware is secure.

Insulation · Satisfactory. Blown-in fiberglass, about 12 inches deep. Bathroom fans vent to the exterior.

Electrical: branch circuits and outlets

Interior outlets · Satisfactory. A sample of outlets in each room tested correctly for polarity and ground.

Light fixtures · Satisfactory. Fixtures and switches operated normally.

Heating: furnace

Furnace · Satisfactory. Gas furnace, 80,000 BTU, about 9 years old. Service sticker shows it was serviced in March 2026. Filter is clean.

Venting · Satisfactory. Flue connections are sealed and slope up toward the chimney.

Heating: overview

Heating system · Satisfactory. Gas forced-air furnace with ducted supply to every room. Thermostat responded to calls for heat.

Plumbing: water heater

Water heater · Monitor. Gas water heater, 40 gallons, about 11 years old. Strapping present. Typical service life is 10 to 15 years; budget for replacement.

Cooling

Air conditioner · Satisfactory. Split system, 3 tons, about 9 years old. Temperature drop across the coil measured 18°F.

Plumbing: supply and drains

Supply piping · Satisfactory. Copper supply lines. Water pressure measured 62 psi at the hose bib.

Drains · Satisfactory. All fixtures drained without backup.

Kitchen

Appliances · Satisfactory. Range, dishwasher and disposal operated normally.

Sink and counters · Satisfactory. Sink is sealed at the counter. No leaks under the sink.

Laundry

Dryer vent · Satisfactory. Rigid metal duct vents to the exterior. Lint screen is clean.

Bathrooms: primary

Shower and tub · Satisfactory. Grout and caulk are intact. Drain flows freely.

Ventilation · Satisfactory. Exhaust fan operates and vents to the exterior.

Bathrooms: hall and half bath

Fixtures · Satisfactory. Toilets are secure to the floor. Sinks drain normally.

Interior: floors, walls and ceilings

Floors · Satisfactory. Hardwood on the main floor and carpet upstairs show normal wear.

Walls and ceilings · Satisfactory. No stains or cracks that suggest moisture or movement.

Interior: doors and stairs

Stairs · Satisfactory. Handrail is continuous and secure. Balusters are spaced less than 4 inches apart.

Fireplace and chimney

Fireplace · Satisfactory. Wood-burning fireplace with a working damper. Recommend a chimney sweep before first use.

Smoke and carbon monoxide alarms

Alarms · Satisfactory. Smoke alarms present in each bedroom and hallway. Carbon monoxide alarm present on each floor.

Crawlspace

Vapor barrier · Satisfactory. Plastic vapor barrier covers the soil. No standing water.

Landscaping and drainage

Trees and shrubs · Satisfactory. Vegetation is trimmed back from the siding and roof.

Driveway and walkways

Driveway · Satisfactory. Concrete driveway with minor settlement cracks typical for its age.

Fences and gates

Fence · Satisfactory. Wood fence is upright. Side gate latches.

Maintenance notes

- Replace the furnace filter every three months.
- Clean gutters each fall and spring.
- Test smoke and carbon monoxide alarms monthly.
- Recaulk tubs and showers when gaps appear.

Standards of practice and limitations

This inspection follows the standards of practice of the state home inspector association. It is a visual, non-invasive inspection of readily accessible systems and components on the day of inspection.

The inspector does not move furniture, open walls or predict future conditions. This report is not a warranty or a guarantee.

Inspector certification

I certify that I personally inspected the property and that this report reflects my findings on the date of inspection.

_____

Inspector signature on file

Bay Area Inspections · sample report · Saturday, October 11, 2026