









- ➊ Align template with wall surface ➋ Use 2.5MM drill bit at indicated markings ➌ Use optional spacers
Secure screws with industrial adhesive into the wall ➍ Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- ➊ Align template with wall surface ➋ Use 2.5MM drill bit at indicated markings ➌ Use optional spacers
Secure screws with industrial adhesive into the wall ➍ Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- ➊ Align template with wall surface ➋ Use 2.5MM drill bit at indicated markings ➌ Use optional spacers
Secure screws with industrial adhesive into the wall ➍ Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- ➊ Align template with wall surface ➋ Use 2.5MM drill bit at indicated markings ➌ Use optional spacers
Secure screws with industrial adhesive into the wall ➍ Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1


- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface
- 2 Use 2.5MM drill bit at indicated markings
- 3 Use optional spacers Secure screws with industrial adhesive into the wall
- 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface
- 2 Use 2.5MM drill bit at indicated markings
- 3 Use optional spacers Secure screws with industrial adhesive into the wall
- 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface
- 2 Use 2.5MM drill bit at indicated markings
- 3 Use optional spacers Secure screws with industrial adhesive into the wall
- 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface
- 2 Use 2.5MM drill bit at indicated markings
- 3 Use optional spacers Secure screws with industrial adhesive into the wall
- 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply



- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1


- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply



- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall 4 Connect to a 12-16V AC or DC power supply




- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall
4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall
4 Connect to a 12-16V AC or DC power supply




© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall
4 Connect to a 12-16V AC or DC power supply



© 2012 luxello V.1.1

- 1 Align template with wall surface 2 Use 2.5MM drill bit at indicated markings 3 Use optional spacers
Secure screws with industrial adhesive into the wall
4 Connect to a 12-16V AC or DC power supply



© 2012 luxello V.1.1