## Raw Point

A Raw Point can be defined as a Digital Input, a Digital Output, an Analog Input, or an Analog Output.

