## 1.5.1 Subparts

- Subpart A (§§75.1-75.8) defines the purpose of the regulation and the extent of its applicability. Subpart A also includes general Acid Rain Program provisions, compliance dates, prohibitions, and lists various methodologies (e.g., ASTM, ASME, etc.) that are incorporated into the rule by reference.
- Subpart B (§§75.10–75.19) presents the general emission monitoring requirements for each pollutant ( $SO_2$ ,  $NO_x$ , etc.). Special instructions are given for monitoring at common stack and multiple stack exhaust configurations.
- Subpart C (§§75.20-75.24) presents the process for certification and recertification of the required continuous monitoring systems, provides the quality assurance and quality control (QA/QC) requirements for the systems, defines "out-of-control" periods, and requires bias adjustment of data from  $SO_2$ ,  $NO_x$ , and flow monitors.
- Subpart D (§§75.30-37) describes the missing data procedures that are used to determine the appropriate substitute data values, for unit operating hours in which the monitoring systems fail to provide quality-assured data.
- Subpart E (§§75.40-75.48) describes the requirements that must be met for approval of an alternative monitoring system.
- Subpart F (§§75.50-75.59) contains the recordkeeping requirements
- **Subpart G** (§§75.60-75.67) contains the reporting requirements. Instructions are provided for submitting notifications, monitoring plans, certification applications, emissions reports, and special petitions to the Administrator.
- Subpart H (§§75.70-75.75) describes the  $NO_x$  mass emission monitoring requirements for sources in  $NO_x$  mass emissions reduction programs that adopt Part 75, such as the annual and ozone season  $NO_x$  trading programs under the CAIR rule. Special instructions are provided for sources that report data only during the ozone season.