## Trend Zoom

Clicking and dragging the mouse over an area of the trend graph allows the end-user to draw a box that will zoom in to provide more finite detail. Double-clicking will return the screen to the default zoom level.