## **OVERVIEW**

The *Calibrations Tab* is used for verifying and controlling analyzers and probes<sup>1</sup>. The *Calibrations Tab*, as seen in <u>Figure Error!</u> No text of specified style in document.-1, is much like the *Overview Tab* in that the right-side pane contains all of the units for the site, and selecting those units will change the *Calibrations Tab* contents.




Figure Error! No text of specified style in document.-1 Calibrations Tab

The center pane of the *Calibrations Tab*, as seen in <u>FIGURE ERROR!</u> No text of specified style in document.-2, contains data lists presenting all of the calibration items for the selected unit. The enduser information such as the status of the last instrument calibration; when the calibration took place, whether or not the instrument is online, and whether the instrument passed calibration; along with expected values, measured values, limits, and other pertinent information regarding the instrument's calibration procedure.

<sup>&</sup>lt;sup>1</sup> Depending on roles and rights user may not have the listed options.




Figure Error! No text of specified style in document.-2 Calibrations Information

The items can be drilled into, as explained in <u>ERROR! REFERENCE SOURCE NOT FOUND.</u> and <u>ERROR! REFERENCE SOURCE NOT FOUND.</u>, to allow for further detail and actions, as seen in <u>FIGURE ERROR!</u> No text of specified style in document.-3.




Figure Error! No text of specified style in document.-3 Calibrations Tab Drill-Down

By clicking on the *Last Calibration Results* expansion button, as seen in <u>FIGURE ERROR!</u> No text of specified style in document.-4, the end-user can obtain a historical look at past calibrations for the instrument.




Figure Error! No text of specified style in document.-4 Last Calibration Results