2.1 Register the Affected Unit(s) with EPA.

Each affected unit must be registered with EPA's Clean Air Markets Division (CAMD) before any data is reported for the unit. Registration can be done electronically, through the CAMD Business System. As part of the registration process, a Designated Representative ("DR") must be assigned for each unit. At the discretion of the company, an Alternate Designated Representative (ADR) may also be assigned. The Designated Representative (or the ADR, in absence of the DR) takes the responsibility for ensuring that each affected unit complies with all of the applicable program requirements, and that the emissions data reported to EPA are true and accurate. For units subject to both the Acid Rain Program and to one or more of the SO₂ and NO_x trading programs under CAIR, the Designated Representative for all of these programs must be the same person.