

Rule Book — Set Speeds Quick Reference

GERT8000 · TW1 Iss 22 · TW5 Iss 14 · SS Iss 13 · T3 Iss 13 · TW7 · TW8 · AC

At Caution (TW1 s25): Proceed at a speed that takes account of conditions — distance you can see to be clear, rail conditions, weather and visibility — allowing you to stop short of any train, vehicle, obstruction or end of movement authority. Must not exceed any speed limit also in force.

PERMISSIBLE SPEED

NORMAL LINE SPEED — SECTIONAL APPENDIX

SS / TW5

PSAD — single line working, correct direction

Travelling in the right direction during SLW — may proceed at up to permissible speed

SS s4.2c

PSAD — pilot working (single or bi-directional line)

Operating under pilotman working — may proceed at up to permissible speed

SS s4.2c

Defective AWS or DSD — competent person provided

CP in cab — proceed at normal permissible speed (reduces to 40 mph in poor visibility)

TW5 s9/s11

AT CAUTION

VARIABLE — STOP SHORT OF ANY OBSTRUCTION

TW1 s25

Passing a signal at danger (default)

Unless authorised to proceed at up to 50 mph — default is always at caution

SS s4.2a

Examining the line ahead

Must proceed over the affected portion at caution

TW1 s12.1

Level crossing — told to approach at caution

Approach at caution and pass over only when safe to do so

TW7/TW8

Movements within a Protection Zone

All movements at caution throughout the PZ

T3

EBW — approach points/crossings (first train)

First train into EBW section must approach all points at caution

SS s4.1

Propelling movements

At caution throughout — also must not exceed 20 mph

TW1 s26.4

Absolute block — after failed train removed

Next train proceeds at caution through the cleared section

SS s1.1

3 mph

MAXIMUM

EMR Local

Depot — wheel lathe, wash plant and fuel line roads

Must not exceed 3 mph when approaching or passing through wheel lathe, wash plant and fuel line roads in depot

EMR local

5 mph

MAXIMUM

TW1 / T3 / SS2

Pass under a struck overline bridge

No obvious damage or debris — proceed under the bridge at no more than 5 mph

TW1 s16

Movement in a possession worksite

No greater than 5 mph within the worksite unless the ES gives specific instructions

T3 s9

Siding, maintenance depot or stabling area

Must not exceed 5 mph in any siding, maintenance depot, servicing or stabling area

SS2

Floodwater up to top of rail head

May continue if water is no deeper than top of rail head — must not exceed 5 mph

M3

10 mph

MAXIMUM

SS / TW1 / TW5

Through any tunnel — PSAD movement or line examination

Must not exceed 10 mph through a tunnel when passing signal at danger or examining the line

SS s7.3 / TW1 s12.1

Through tunnel — divided train recovery

When told to proceed at caution past affected location and tunnel is in that section

TW1 s14

Propelling / dead train movements (general max)

Maximum speed during movement — reduces to 5 mph over points and crossings

TW5 s6

Brakes not fully released

If brakes cannot be fully released — 10 mph max, 5 mph over points and crossings

TW5 s3

15 mph

MAXIMUM

SS

Points/crossings during PSAD movement

Must not pass over any points, switch diamonds or swing-nose crossings at more than 15 mph

SS s7.3

Points/crossings — EBW, first train into section

After approaching at caution and checking position, must not exceed 15 mph over points

SS s4.1

20 mph	TW1 / TWS / AC
MAXIMUM	
Suspected track defect — line examination Signaller advises examination is because of a suspected track defect TW1 s12.1	
Hot axle box — failed exam, 2nd or lineside activation Cannot examine within 10 min / 2nd activation / lineside detection — proceed at no more than 20 mph TW5 s9	
AC — OLE examined from adjacent line, no defect found Next electric train on the affected line must proceed at caution not exceeding 20 mph AC s15	
AC — Driver asked to examine the overhead line Proceed at caution not exceeding 20 mph while looking for damage to the OLE AC s15	
AC — Passed 'do not raise pantograph' sign without raising Must reduce speed to 20 mph before attempting to raise the pantograph AC s15	

25 mph	T3 / M2
MAXIMUM	
All movements entering, within or leaving a possession Must not exceed 25 mph at any point — movements inside the worksite are capped at 5 mph T3 s9	
Assisting train moving towards a failed train Proceed at caution not exceeding 25 mph during the movement towards the failed train M2 s3.3	

40 mph	TW1 / TWS
MAXIMUM	
Poor visibility — line where AWS is not provided Cannot see signals in time during poor visibility; no AWS on this line (Sectional Appendix Table A) TW1 s22	
Hot axle box / defective AWS or DSD — poor visibility Even with competent person provided, must not exceed 40 mph during poor visibility TW5 s9/s11	

50 mph	S5 / TWS
MAXIMUM	
PSAD — authorised to proceed at up to 50 mph SLW wrong direction; emergency permissive working; certain other S5 s4.2b circumstances S5 s4.2b	
Extended Block Working (EBW) — section maximum Must not exceed 50 mph at any point throughout the EBW section S5 s5	
Points/crossings in EBW — if specifically permitted May pass over points at up to 50 mph only if given permission during EBW S5 s4.1	
Defective AWS/DSD — freight or OTM (no competent person) Freight and OTMs without CP — proceed to next location at no more than 50 mph TW5 s9/s11	

60 mph	TWS
MAXIMUM	
Defective AWS/DSD — passenger train (no competent person) Passenger trains without CP — proceed to next location at no more than 60 mph TW5 s9/s11	
Radio network failure — through the affected area When told of a radio network failure, max speed through the affected area is 60 mph TW5 s13	

75 / 80 / 100 mph	TWS · AC
MAXIMUM	
75 mph — defective headlight, portable headlight fitted No other headlight available — train may only start if portable headlight fitted; speed restricted to 75 mph TW5 s12	
80 mph — raising pantographs (AC lines) You may raise pantographs at any speed up to 80 mph, or higher if authorised by company instructions AC s5	
100 mph — radio network failure (overall line max) May be told not to exceed 100 mph on the line; 60 mph specifically through the affected radio area TW5 s13	