

# ENGR10003 – Engineering Systems Design 2

## Assignment Cover Sheet

**Assignment Title:** Mechanics Assignment 1

### Plagiarism

Plagiarism is the act of representing as one's own original work the creative works of another, without appropriate acknowledgment of the author or source.

### Collusion

Collusion is the presentation by a student of an assignment as his or her own which is in fact the result in whole or in part of unauthorised collaboration with another person or persons. Collusion involves the cooperation of two or more students in plagiarism or other forms of academic misconduct.

Both collusion and plagiarism can occur in group work. For examples of plagiarism, collusion and academic misconduct in group work please see the University's policy on Academic Honesty and Plagiarism:

<https://academichonesty.unimelb.edu.au>

**Plagiarism and collusion constitute cheating. Disciplinary action will be taken against students who engage in plagiarism and collusion as outlined in University policy. Proven involvement in plagiarism or collusion may be recorded on my academic file in accordance with Statute 13.1.18.**

### Student Declaration

I/We acknowledge that:

- This assignment is my/our own original work, except where I/we have appropriately cited the original source.
- This assignment has not previously been submitted for assessment in this or any other subject.
- This assessment item is the work of the undersigned.
- All contributors are listed below.
- Students who have not contributed are not listed.
- Only students listed on this cover sheet will be awarded marks for this assignment.
- This cover sheet was completed upon completion of this assessment item.

For the purposes of assessment, I give the assessor of this assignment the permission to:

- Share this assignment with other staff members; and
- Take steps to authenticate the assignment, including communicating a copy of this assignment to a checking service (which may retain a copy of the assignment on its database for future plagiarism checking).

### Student Details

Print Name	Student No.	Signature	Date
Catherine Lloyd	1178494	CATHERINE LLOYD	19/10/2020
James La Fontaine	1079860	JAMES LA FONTAINE	19/10/2020
Zak Kanwischer	1085850	ZAK KANWISCHER	19/10/2020

### Question 1

a) Springs in series and in parallel:

$$\begin{aligned} \text{in parallel} \\ k_{\text{eq}(p)} &= k_1 + k_2 \\ \Rightarrow k_{\text{eq}(p)} &= 2k_1 \end{aligned}$$

$$\begin{array}{c} \text{in series} \\ \frac{1}{k_{\text{total}}} = \frac{1}{k_1} + \frac{1}{k_2} \end{array}$$

$$\begin{aligned} F &= k_{\text{total}} x \\ \Rightarrow \frac{1}{k_{\text{total}}} &= \frac{x}{F} \end{aligned}$$

$$\begin{aligned} K_{\text{eq}} &= \frac{2k_1 k_2}{k_1 + 2k_2} \quad (2k_1 < k_2) \\ \frac{1}{k_{\text{total}}} &= \frac{1}{k_1} + \frac{1}{2k_2} \\ \Rightarrow \frac{x}{F} &= \frac{1}{k_1} + \frac{1}{2k_2} \\ \Rightarrow x k_1 k_2 &= (2k_1 + k_2) F \\ \Rightarrow x k_2 k_1 &= 2k_1 F + k_2 F \\ \Rightarrow x k_2 k_1 - 2k_1 F &= k_2 F \\ \Rightarrow k_1 (k_2 x - 2F) &= F k_2 \\ \Rightarrow k_1 &= \frac{F k_2}{k_2 x - 2F} \end{aligned}$$

b)  $k_1 = \frac{F k_2}{k_2 x - 2F}$

$$\Rightarrow k_1 = \frac{(4N)(100N/m)}{2(100N/m)(0.06m) - 2(4N)}$$

$$\Rightarrow k_1 = 100N/m$$

c)  $k_1 = \frac{F k_2}{k_2 x - 2F}$

$$\Rightarrow k_1 = \frac{(4N)(10N/m)}{2(10N/m)(0.06m) - 2(4N)}$$

$$\frac{400}{68} = \frac{200}{34} = \frac{100}{17}$$

$$\Rightarrow k_1 = \frac{40N^2/m}{-6.8N}$$

$$\Rightarrow k_1 = -\frac{100}{17} N/m$$

No realistic answer exists because k values cannot be negative

Question 2

2a)

$$\left. \begin{aligned} T_{Ax}\vec{i} + T_{Bx}\vec{i} - R_x\vec{i} &= 0 \\ T_{Ay}\vec{j} + R_y\vec{j} - T_{By}\vec{j} &= 0 \end{aligned} \right\} \text{as the system is in equilibrium}$$

$$\Rightarrow R_x\vec{i} = T_{Ax}\vec{i} + T_{Bx}\vec{i} \quad (1)$$

$$\Rightarrow R_y\vec{j} = -T_{Ay}\vec{j} + T_{By}\vec{j} \quad (2)$$

$$(1) 4000 \cos(10^\circ) = T_A \cos(15^\circ) + T_B \cos(20^\circ)$$

$$\Rightarrow 4000 \cos(10^\circ) - T_A \cos(15^\circ) = T_B \cos(20^\circ)$$

$$\Rightarrow T_B = \frac{4000 \cos(10^\circ) - T_A \cos(15^\circ)}{\cos(20^\circ)} \quad (3)$$

sub (3) into (2)

$$(2) 4000 \sin(10^\circ) = -T_A \sin(15^\circ) + \left( \frac{4000 \cos(10^\circ) - T_A \cos(15^\circ)}{\cos(20^\circ)} \times \sin(20^\circ) \right)$$

~~approx (20%)~~

$$\Rightarrow 694.593 = -0.2588 T_A + (4192.05 - 1.0279 T_A) \times \sin(20^\circ)$$

$$\Rightarrow 694.593 = -0.2588 T_A + 1433.77 - 0.3516 T_A$$

$$\Rightarrow -739.177 = -0.6104 T_A$$

$$\boxed{\Rightarrow T_A = 1210.97 \approx 1211 \text{ N}}$$

$$T_B = ?$$

2b) function  $[TA, TB] = \text{calcRangeOfTensions}$

theta = 0 : 0.5 : 20 ;

A = [cosd(15) cosd(20); sind(15) -sind(20)];

for i = 1 : length(theta)

C = [4000 \* cosd(theta(i)); -4000 \* sind(theta(i))];

X = inv(A) \* C;

TA(i) = X(1);

TB(i) = X(2);

end

plot(theta, TA, 'rs', theta, TB, 'go');

grid on

xlabel("theta (degrees)");

ylabel("F(N)");

end

Yes, the tensions have an equal magnitude  
of 2097N with  $\Theta = 2.5^\circ$

### Question 3

3a) length of unstretched spring is  $l_0$

$$l_{AD} = l_{OA} + l_0$$

$$\Rightarrow l_0 = l_{AD} - l_{OA}$$

$$\Rightarrow l_0 = 480\text{mm} - 250\text{mm}$$

$$\boxed{\Rightarrow l_0 = 230\text{mm}}$$

b)  $l_{AD}$  = length of unstretched spring

let  $l_{ADx}$  be horizontal component of  $l_{AD}$

let  $l_{ADy}$  be vertical component of  $l_{AD}$

$$l_{AD} = \sqrt{(l_{ADx})^2 + (l_{ADy})^2}$$

$l_0$  = length of unstretched spring

since  $l_0 = l_{AD} - l_{OA}$ ,

$$l_{ADx} = l_{AD} - l_{OA} \cdot \cos \theta$$


since spring attaches from A to D (same vertical level as O),  
vertical component of  $l_{OA}$  is vertical component of spring

$$\Rightarrow l_{ADy} = l_{OA} \cdot \sin \theta$$

$$\therefore \boxed{l_{AD} = \sqrt{(l_{ADx})^2 + (l_{ADy})^2}}$$

c)  $l_{AD}$  = length of stretched spring

$l_{OA} \cdot \sin \theta$  = vertical component of stretched spring  
 $\alpha$  = angle between stretched spring and horizontal component of spring



$$\Rightarrow \sin(\alpha) = \frac{l_{OA} \cdot \sin \theta}{l_{AD}}$$

$$\Rightarrow \boxed{\alpha = \arcsin \left( \frac{l_{OA} \cdot \sin \theta}{l_{AD}} \right)}$$


d)  $x$  = change in length of spring

$$\Rightarrow x = \text{length of stretched spring} - \text{length of unstretched spring}$$

$$\Rightarrow x = l_{AD} - l_0$$

$$\Rightarrow \boxed{F_s = kx}$$

3e.



$$\cancel{M_G} = 10 \times 9.81 \times \cos \theta \times l_0 g$$

$$M_C = 3 \times 9.81 \times \cos \theta \times l_{AC} g$$

To find moment due to the spring:

Use  $M_s = \pm |F_s r_{xy}| \pm |F_y r_{xz}|$  where:

$$F_x = F_s \cos \alpha$$

$$F_y = F_s \sin \alpha$$

$$r_y = l_{AD} \sin \alpha$$

$$r_{xz} = l_{AD} - l_{AD} \cos \alpha$$

$$M_s = l_{AD} \sin \alpha (F_s \cos \alpha) - F_s \sin \alpha (l_{AD} - l_{AD} \cos \alpha)$$

Overall moment: about point O


$$M = 10 \times 9.81 \times \cos \theta \times l_0 g + 3 \times 9.81 \times \cos \theta \times l_{AC} g$$

$$+ l_{AD} \sin \alpha (F_s \cos \alpha) - F_s \sin \alpha (l_{AD} - l_{AD} \cos \alpha)$$

For static equilibrium,  $M = 0$ :

$$0 = M_G + M_C + M_s$$

### 3f) Graph of theta vs M



#### Code:

```
theta=[0:180]
lo=230e-3
lod=480e-3
log=150e-3
loa=250e-3
loc=360e-3
k=1200
lad=sqrt((lod-loa.*cosd(theta)).^2+(loa.*sind(theta)).^2)
a=asind(loa.*sind(theta)./lad)
Fs=k.*(lad-lo)
m1=10
m2=3
g=9.81

Mg=-m1.*g.*cosd(theta).*log
Mc=-m2.*g.*cosd(theta).*loc
Ms=lad.*sind(a).*Fs.*cosd(a)+Fs.*sind(a).*(lod-lad.*cosd(a))

M=Mg+Mc+Ms

plot(theta,M, 'r-')
grid on
grid minor
```


3g)  $M=0$  for  $\theta = 34.5^\circ$

The minimum moment = -25 at  $0^\circ$


The maximum moment = 93.5 at  $114^\circ$

#### Question 4

4a)



Force diagram



#### Joint A

Sum of forces in  $x$  direction is zero

$$\sum F_x = RAx + N_{AB} \cdot \cos \theta + N_{AE}$$

Sum of forces in  $y$  direction is zero

$$\sum F_y = RAY + N_{AB} \sin \theta = 0$$

### Joint B

Sum of forces in x direction is zero

$$\sum F_x = F_1 \cos \alpha + N_{BC} + N_{BE} \cos \theta - N_{AB} \cos \theta = 0$$

Sum of forces in y direction is zero

$$\sum F_y = -F_1 \sin \alpha - N_{BE} \sin \theta - N_{AB} \sin \theta = 0$$

### Joint C

Sum of forces in x direction is zero

$$\sum F_x = -N_{BC} - N_{CE} \cos \theta + N_{CD} \cos \theta$$

Sum of forces in y direction is zero

$$\sum F_y = -N_{CE} \sin \theta - N_{CD} \sin \theta = 0$$

### Joint D

Sum of forces in x direction is zero

$$\sum F_x = -N_{DE} - N_{CD} \cos \theta = 0$$

Sum of forces in y direction is zero

$$\sum F_y = R_D y + N_{CD} \sin \theta = 0$$

### Joint E

Sum of forces in x direction is zero

$$\sum F_x = -N_{AE} + N_{DE} - N_{BE} \cos \theta + N_{CE} \cos \theta + f_2 \sin \beta = 0$$

Sum of forces in y direction is zero

$$\sum F_y = -f_2 \cos \beta + N_{BE} \sin \theta + N_{CE} \sin \theta = 0$$

## Matrix form


$$\begin{array}{l}
 R_{AX} \quad R_{AY} \quad N_{AB} \quad N_{AE} \quad N_{BC} \quad N_{BE} \quad N_{CE} \quad N_{CD} \quad N_{DE} \quad R_{Dy} \\
 \left[ \begin{array}{ccccccccc|c}
 1 & 0 & \cos\theta & 1 & 0 & 0 & 0 & 0 & 0 & 0 \\
 0 & 1 & \sin\theta & 0 & 0 & 0 & 0 & 0 & 0 & 0 \\
 0 & 0 & -\cos\theta & 0 & 1 & \cos\theta & 0 & 0 & 0 & -F_1 \cos\alpha \\
 0 & 0 & -\sin\theta & 0 & 0 & -\sin\theta & 0 & 0 & 0 & F_1 \sin\alpha \\
 0 & 0 & 0 & 0 & -1 & 0 & -\cos\theta & \cos\theta & 0 & 0 \\
 0 & 0 & 0 & 0 & 0 & 0 & -\sin\theta & -\sin\theta & 0 & 0 \\
 0 & 0 & 0 & 0 & 0 & 0 & 0 & -\cos\theta & -1 & 0 \\
 0 & 0 & 0 & 0 & 0 & 0 & 0 & \sin\theta & 0 & 1 \\
 0 & 0 & 0 & -1 & 0 & -\cos\theta & \cos\theta & 0 & 1 & 0 \\
 0 & 0 & 0 & 0 & 0 & \sin\theta & \sin\theta & 0 & 0 & 0 \\
 \end{array} \right] = \begin{array}{l}
 R_{AX} \\
 R_{AY} \\
 N_{AB} \\
 N_{AE} \\
 N_{BC} \\
 N_{BE} \\
 N_{CE} \\
 N_{CD} \\
 N_{DE} \\
 R_{Dy}
 \end{array} = \begin{array}{l}
 0 \\
 0 \\
 -F_1 \cos\alpha \\
 F_1 \sin\alpha \\
 0 \\
 0 \\
 0 \\
 0 \\
 0 \\
 -F_2 \sin B \\
 F_2 \cos B
 \end{array}
 \end{array}$$

Therefore:

$$\left[ \begin{array}{ccccccccc|c}
 1 & 0 & \cos\theta & 1 & 0 & 0 & 0 & 0 & 0 & 0 \\
 0 & 1 & \sin\theta & 0 & 0 & 0 & 0 & 0 & 0 & 0 \\
 0 & 0 & -\cos\theta & 0 & 1 & \cos\theta & 0 & 0 & 0 & 0 \\
 0 & 0 & -\sin\theta & 0 & 0 & -\sin\theta & 0 & 0 & 0 & 0 \\
 0 & 0 & 0 & 0 & -1 & 0 & -\cos\theta & \cos\theta & 0 & 0 \\
 0 & 0 & 0 & 0 & 0 & 0 & -\sin\theta & -\sin\theta & 0 & 0 \\
 0 & 0 & 0 & 0 & 0 & 0 & 0 & -\cos\theta & -1 & 0 \\
 0 & 0 & 0 & 0 & 0 & 0 & 0 & \sin\theta & 0 & 1 \\
 0 & 0 & 0 & -1 & 0 & -\cos\theta & \cos\theta & 0 & 1 & 0 \\
 0 & 0 & 0 & 0 & 0 & \sin\theta & \sin\theta & 0 & 0 & 0
 \end{array} \right] = \left\{ \begin{array}{l}
 R_{AX} \\
 R_{AY} \\
 N_{AB} \\
 N_{AE} \\
 N_{BC} \\
 N_{BE} \\
 N_{CE} \\
 N_{CD} \\
 N_{DE} \\
 R_{Dy}
 \end{array} \right\} = \left\{ \begin{array}{l}
 0 \\
 0 \\
 -F_1 \cos\alpha \\
 F_1 \sin\alpha \\
 0 \\
 0 \\
 0 \\
 0 \\
 0 \\
 -F_2 \sin B \\
 F_2 \cos B
 \end{array} \right\}$$

Solving this equation gives all the forces in the truss structure.

4b) The moment (total) of the truss must be zero, so treating it as a rigid body:  $a = B = 0$ ,  $F_1 = 6000 \text{ N}$ ,  $F_2 = 8000 \text{ N}$



The horizontal and vertical forces must also sum to zero, so:

$$0 = -8000 + R_{Dy} + R_{Ay} \quad (1)$$

$$0 = 6000 + R_{Ax}, \quad R_{Ax} = -6000 \text{ N.} \quad (2)$$

Using point A to calculate the moment:

$$M_A = 6000 \times 4 + 8000 \times 6 + 12 \times R_{Dy}$$

Since the moment must be zero:

$$0 = 6000 \times 4 + 8000 \times 6 + 12 R_{Dy}$$

$$\text{So } R_{Dy} = 6000 \text{ N}$$

And using eqn (1),  $8000 = R_{Dy} + R_{Ay}$

$$\text{So } R_{Ay} = 2000 \text{ N.}$$

4c) Using the equations from (a) and the values from (b):

$$-6000 + N_{AB} \cos\theta + N_{AE} = 0 \quad (1)$$

$$2000 + N_{AB} \sin\theta = 0 \quad (2)$$

$$-N_{AB} \cos\theta + N_{BC} + N_{BE} \cos\theta = -6000 \cos(\theta) \quad (3)$$

$$-N_{AB} \sin\theta - N_{BE} \sin\theta = 6000 \sin(\theta) \quad (4)$$

$$-N_{BC} - N_{CE} \cos\theta + N_{CD} \cos\theta = 0 \quad (5)$$

$$-N_{CE} \sin\theta - N_{CD} \sin\theta = 0 \quad (6)$$

$$-N_{CD} \cos\theta - N_{DE} = 0 \quad (7)$$

$$N_{CD} \sin\theta + 6000 = 0 \quad (8)$$

$$-N_{AE} - N_{BE} \cos\theta + N_{CE} \cos\theta + N_{DE} = -8000 \sin(\theta) \quad (9)$$

$$N_{BE} \sin\theta + N_{CE} \sin\theta = 8000 \cos(\theta) \quad (10)$$

Using (2) and (8):  $N_{CD} = \frac{-6000}{\sin\theta}$

$$N_{AB} = -\frac{2000}{\sin\theta}$$

Using (1):  $-6000 - \left(\frac{2000}{\sin\theta}\right) \cos\theta + N_{AE} = 0$

$$N_{AE} = 6000 + \frac{2000 \cos\theta}{\sin\theta}$$

Using (9):  $\left(\frac{2000}{\sin\theta}\right) \sin\theta - N_{BE} \sin\theta = 0$

$$N_{BE} = \frac{2000}{\sin\theta}$$

Using (6):  $-N_{CE} \sin\theta - \left(\frac{-6000}{\sin\theta}\right) \sin\theta = 0$

$$N_{CE} = \frac{6000}{\sin\theta}$$


Using (7):  $-\left(\frac{-6000}{\sin\theta}\right) \cos\theta - N_{DE} = 0$

$$N_{DE} = \frac{6000 \cos\theta}{\sin\theta}$$

Using (3):  $\frac{2000}{\sin\theta} (\cos\theta) + N_{BC} + \left(\frac{2000}{\sin\theta}\right) \cos\theta = -6000$

$$N_{BC} = -\frac{4000 \cos\theta}{\sin\theta} - 6000$$

Using the diagram:



$$\text{So } \tan \theta = \frac{4}{3}$$

$$\theta = \arctan\left(\frac{4}{3}\right)$$

Using  $\theta$  and the equations find:

$$N_{AB} = -2500 \quad \text{---}$$

$$N_{AE} = 7500 \quad \text{---}$$

$$N_{BC} = -9000 \quad \text{---}$$

$$N_{BE} = 2500 \quad \text{---}$$

$$N_{CE} = 7500 \quad \text{---}$$

$$N_{CD} = -7500 \quad \text{---}$$

$$N_{DE} = 4500 \quad \text{---}$$

4e) First checking the maximum stretch = 7500 N

$$\sigma_u = 110 \times 10^6 = \frac{F}{A} \quad \text{Each side minimum}$$

$$110 \times 10^6 = \frac{7500}{\pi r^2} \quad 8.26 \text{ mm.}$$

$$\therefore r = 0.00826 \text{ m for.}$$

But also checking maximum compression = 9000 N.

Assuming it will buckle past 9000 N:

$$F = \frac{\pi^2 EI}{L^2} \quad \text{where } L \text{ is the longest length} = 6 \text{ m.}$$

$$9000 = \frac{\pi^2 \times 70 \times 10^9 \times I}{36} \quad I = \frac{d^4}{12} \quad \text{for a square cross section}$$

$$9000 = \frac{\pi^2 \times 70 \times 10^9 \times d^4}{36 \times 12}$$

$$d = 0.0987 \text{ m} \quad \text{so the beam must have dimension min. } 9.87 \text{ cm} \times 9.87 \text{ cm}$$

### Code for 4d- yielded the same results as calculated in 4c

```
clear all
i=atan(4/3)
F1=6000
F2=8000
a=0
b=0
eqns=[1 0 cos(i) 1 0 0 0 0 0 0;
      0 1 sin(i) 0 0 0 0 0 0 0;
      0 0 -cos(i) 0 1 cos(i) 0 0 0 0;
      0 0 -sin(i) 0 0 -sin(i) 0 0 0 0;
      0 0 0 0 -1 0 -cos(i) cos(i) 0 0;
      0 0 0 0 0 0 -sin(i) -sin(i) 0 0;
      0 0 0 0 0 0 -cos(i) -1 0;
      0 0 0 0 0 0 sin(i) 0 1;
      0 0 0 -1 0 -cos(i) cos(i) 0 1 0;
      0 0 0 0 sin(i) sin(i) 0 0 0]
ans=[0;0;-F1*cos(a);F1*sin(a);0;0;0;0;-F2*sin(b);F2*cos(b)]
res=inv(eqns)*ans

Rax=res(1)
Ray=res(2)
Nab=res(3)
Nae=res(4)
Nbc=res(5)
Nbe=res(6)
Nce=res(7)
Ncd=res(8)
Nde=res(9)
Rdy=res(10)
```

### Question 5

```
function [u0, v0] = GetVelocityFromSetup(lrest,lmax,lmin,k,L)
N = length(k);
xmax = zeros(1,N);
xmin = zeros(1,N);
Espring = zeros(1,N);
Etotal = 0;
mball = 0.0127;
lball = 0.53;
larm = 0.51;
marm = 0.388;

% calculate xmax and xmin for each spring
for i = 1:N
    xmax(i) = lmax(i) - lrest(i);
    xmin(i) = lmin(i) - lrest(i);
end

% calculate the energy for each spring and sum up the energy of each
% spring to get the total energy
for i = 1:N
    Espring(i) = 0.5*k(i)*(xmax(i)^2-(xmin(i))^2)+L(i)*(xmax(i)-xmin(i));
    Etotal = Etotal + Espring(i);
end

% calculate the moment of inertia
Iarm = (1/3)*marm*larm^2;
Iball = mball*lball^2;
```

```
% calculate the total moment of inertia and use it to calculate the
% angular velocity
I = Iarm + Iball;
ang_vel = sqrt((2*Etotal)/I);

% calculate u0 and v0
V0 = ang_vel*lball;
u0 = V0*cosd(45);
v0 = V0*sind(45);
end
```