

EXP-0001 ramp failure: static content and weak inertial excitation

