

 SCG, URSC	Minutes of Software DRC Meeting SCG Checkout Software Systems' DRC	Doc. No: SCG-FM-GEN-MM Issue Date: 01-March-2017 Issue: A Rev: 00
		Page 1 of 2

Chairman of Software DRC	Ms. Muthumani Rajan
Agenda	To review the close-out note of action items minuted during design review meeting (DRC) for the software, <i>SPAcecraft Status Display And Commanding Software (SPASDACS) 1.0</i> .
Member secretary	Ms. Sheena Jose
Attendees	Nil
Enclosures	Close-out Note on the action items minuted on 03-11-2021 Updated SRS, SDD & Test Report document

DRC review of the software, SPAcecraft Status Display And Commanding Software (SPASDACS) 1.0 was held in two sittings on 08-10-2021 & 26-10-2021.

Designers had provided the close-out note on the action items minuted along with the updated SDD documents, which was reviewed by committee.

A demo of the software in RISAT-1A Checkout with IST data was given by designers as requested by the DRC review committee.

The following are the observations during the demo.

No.	Deliberations	Actionee	Status
1.	Software was giving a very good visual representation of the Power subsystem status to the Users in RISAT-1A checkout.	NA	Information
2.	Correctness of the visual representation purely depends on how Users have defined the attributes of each visual element and the parameters linked with values for success and failure conditions.		
3.	SPASDACS software provides a generalized platform with lot of flexibility and features to the users for visual representation of Spacecraft subsystem. Hence, Committee recommends that there should a mechanism to review and verify the correctness of the visual configuration of the display by the Checkout team for a specific project.		

 SCG, URSC	Minutes of Software DRC Meeting SCG Checkout Software Systems' DRC	Doc. No: SCG-FM-GEN-MM Issue Date: 01-March-2017 Issue: A Rev: 00
		Page 2 of 2

No.	Deliberations	Actionee	Status
4.	The Alarms tab displayed the deviations of Analog parameters only against the limit. Designers shall augment the software for Digital parameters also in the next version.	Designers	Information
5.	During the demo, it was observed that the one visual element (SPS status) was showing erroneous status (RED color). While viewing, the reason for the erroneous status was not directly displayed. Quick look of the erroneous reason on mouse over can be implemented in the next version	Designers	Information
6.	All DRC suggestions will be evaluated for implementation in the next software version, subject to technical feasibility.		

Committee clears the design aspects of the software.

The Committee recommends for a review by the DPD Checkout of the specific project for the correctness of the visual elements, the mapping of TM/SCOS parameter to the visual elements & other related attributes.

Prepared by	Ms. Sheena Jose	
Reviewed and Approved by	Ms. Muthumani Rajan	
Minutes Issued Date	12-11-2021	
Circulation List	- Attendees of DRC review - Software DRC Committee Members, - DHs & Group Director, SCG	