

JOB INSTRUCTIONS FOR BENDING

- Recommended PPEs to be used.
- Before loading any plates, stoppers stands to be placed to the machine bed.
- Ensure all the stoppers as per dimensions and check with the help of Vernier caliper.
- Load the die with help of the fork lift or jib crane and punch for bending of the job as per drawing.
- Insert the programme as per the drawing required for bending.
- Load the raw material and check right angle of the plate job.
- Give/press the Bending is done as per required dimensions and inspect the randomly.
- Unload the completed job with the help of fork lift or jib crane.
- Add at proper place – check to the E – stop operation before start using.

