

STANDARD OPERATING PROCEDURE FOR DRILLING

- Recommended PPEs to be used.
- Check workspace free from unwanted material.
- Check that the drill chuck guard is in position.
- Ensure the chuck key (if used) has been removed from the drill chuck.
- Locate and ensure you are familiar with the operation of the ON/OFF starter and E-Stop (if fitted).
- Follow correct clamping procedures to ensure work is secure.
- Adjust spindle speed to suit drill or cutter diameter.
- Never leave the Drill Press while it is running.
- Before making adjustments or before cleaning swarf accumulations switch off and bring the machine to a complete standstill.
- Feed downwards at a sufficient rate to keep the drill cutting.
- Feed with care as the drill breaks through the underside of the work.
- Use a safe working posture (beware of hair catching).
- Switch off the machine.