

STANDARD OPERATING PROCEDURE FOR MACHINE SHIFTING

❖ Before installation of machine ensure adequate area to be identified.
❖ Use PPEs Safety Helmet, Safety Shoe, Cotton Hand Gloves.
❖ Proper Layout to be made for placement of machinery.
❖ Before start the job communicate all the hazards and its control measures to the concerned workmen.
❖ Ensure the machine shifting area should be done proper housekeeping.
❖ Adequate safe lifting procedure to be followed for the machinery shifting.
❖ Ensure all the lifting tools and tackles should be in good condition and tested one.
❖ Machine placing area.
❖ Pathways should be cleaned and kept free from materials and scarps.
❖ Operator is responsible for cleaning of oils and coolant spills and it should be cleaned in every shift ending and frequently with in a timeline.
❖ Before doing any hot work near machines the concern production person (Machine operator) should be responsible for cleaning the oils and flammable materials surrounding the machine areas.
❖ Ensure surrounding work areas should be cleaned regularly/daily to ensure a good housekeeping. (pits etc.)