

## **STANDARD OPERATING PROCEDURE FOR GAS CUTTING**

1. **PURPOSE:** In order to avoid accident and reduce the risk while doing Gas Cutting.
2. **SCOPE:** These instructions are applicable to Maintenance.
3. **RESPONSIBILITY:** Maintenance Team, Tool In-charges, Engineer/ HOD
4. **SAFETY:** All safety precautions will be taken during the execution of this Procedure.
5. **SAFE OPERATING PROCEDURE:**
  - 5.1. Wear the Personal Protective Equipment's Safety Helmet, Leather Hand gloves, Safety Goggle, Hand Shield, Leg Guard and Safety Shoe.



- 5.2. Keep the work Piece in the safer area/Work Bench. Ensure no Flammable objects or liquid not available Near by the work place
- 5.3. Keep the Fire Extinguisher around 1 Meter Distance
- 5.4. Open the O<sub>2</sub> and Acetylene Cylinder, Adjust the regulator for required Pressure.
- 5.5. Ensure Flash Back Arrestor availability in the Cutting Torch & Regulator.
- 5.6. Ensure there is no Gas leakage in The Hose & Connector areas

- 5.7.** Slightly open O<sub>2</sub> Valve in the Torch
- 5.8.** Lighten by Using Spark Lighter and adjust the Flame by Opening Acetylene & O<sub>2</sub> Control Valve.
- 5.9.** Place the Torch Near to The Work Piece and Start Heating up to the Work Piece color changing into Red
- 5.10.** Place Torch Near to The Work piece marked area for Cutting
- 5.11.** Keep the Torch at the Starting Point and start heating the marked area.
- 5.12.** After getting red on the edge Slightly Press the Oxygen handle for Pressurized Cutting.
- 5.13.** Once Started Cutting Slightly Move the Torch towards you with Oxygen Handle Pressed condition.
- 5.14.** After Completion of Cutting or Pre heating Close the Torch Valve.
- 5.15.** Keep the Torch in Proper position in the moving Trolley. Ensure Hot nozzle will not touch with Gas Hose.
- 5.16.** Wind the hoses properly.
- 5.17.** Remove the Plug and wind the Cable in the welding Trolley
- 5.18.** Move the machine to location
- 5.19.** Ensure all the tools & Accessories removed from the work place and keep it in

|                     |                     |                     |
|---------------------|---------------------|---------------------|
| <b>Prepared by:</b> | <b>Reviewed by:</b> | <b>Approved by:</b> |
|---------------------|---------------------|---------------------|