



Mechanism diagnostic: package context matters

capped bed: full package fails



Franka link-local package passes

link-local primitives



Recorded audit checks

Settle gate: 0.05 m/s

Isolated target check

target passes

Full bed package

bed package fails

Contact/floor sole cause

rejected

Mass-only explanation

rejected

COM/inertia sensitivity

supported