


Mechanism diagnostic: package context matters



Recorded audit checks

Settle gate: 0.05 m/s

Isolated target check

target passes

Full bed package

bed package fails

Contact/floor sole cause

rejected

Mass-only explanation

rejected

COM/inertia sensitivity

supported