

Week II – Lecture I: Fabrication of Metals

Callister 9^{th} edition Chp 17.1 - 17.4






1

Why be concerned with fabrication techniques?





- Influences material properties
- Incorrect selection/improper methods can result in unexpected material failures
- Economic considerations




Forming operations

Main features:
Shape a metal through plastic deformation Induced by external stress >> yield strength
Most moderately to very ductile metals

Forming

Cold working

Youtube: mparr44114



Cold vs hot working 600 Tensile strength Hot working 50 strength (MPa) Forming temperature > recrystallisation temperature 40 Large deformations possible 400 30 Lower deformation energy requirements No residual stresses Ductility Disadvantages: Surface oxidation Grain growth Recrystallization Poor surface finish High temperature energy input Cold-worked and recovered metalsupermarkets.com metalsupermarkets.comealing temperature (°C)

Forming Forming: Deforming hot metal through repeated blows/squeezing action Closed die: two halves having the finished shape surround the material Open die: simple shapes that do not surround material (larger parts) Advantages: good grain structures and mechanical properties Paging Rolling Extrusion Drawing Forming operations Forming operations Forming operations Forming operations House, Structure and Drawing Forming operations Forming operations


Rolling:


• Metal is thinned due to compressive stresses from rollers


• Cold rolling: Sheet, strip, foils


• Grooved rolling: I-beams and railroad rails


https://commons.wikimedia.org/wiki/File-Rolling.gif (CC 3.0)

























Miscellaneous: Powder metallurgy

Miscellaneous Powder metallurgy

Advantages:

- · Low ductilities
- High melting temperatures
- Close tolerances
- Porosity (self-lubricating bearings)

Disadvantages:

- Porosity can serve as stress raisers for fracture
- Heat treatment and powder atomization is expensive




tehcoparts.en.made-in-china.com

19

Miscellaneous: Welding


- Metallurgical joining of two or more metals to create a single piece
- Examples: arc and gas welding, brazing and soldering
- Local regions of workpieces and filler material (welding rods/wire) is heated until melted
- Molten filler material fills the fusion joint
- High temperatures: heat-affected zone (HAZ)













© The content of this presentation is copyright protected under a Creative Commons Attribution-NonCommercial-NoDerivatives 4.0 International License



COPYRIGHT

Copyright © 2021 Stellenbosch University All rights reserved

DISCLAIMER

This content is provided without warranty or representation of any kind. The use of the content is entirely at your own risk and Stellenbosch University (SU) will have no liability directly or indirectly as a result of this content.

The content must not be assumed to provide complete coverage of the particular study material. Content may be removed or changed without notice.

The video is of a recording with very limited post-recording editing. The video is intended for use only by SU students enrolled in the particular module.