

PCB Prime Headquarters

13900 E. Florida Ave | Suite F | Aurora, CO 80012 Low Cost/High Quality

Contact : Dan Walsh

Email: dan@pcbprime.com

Direct: 503-880-2915 Fax: 303-362-7654

ow Cost/High Qualit Fast Turn Times Aluminum Flex/Rigid Flex HDI/Impedance/VIP

Stencils

Always Free Tooling and Free Electrical Test!

Best Customer Service in the Industry!

It's easy to move your legacy parts to Prime.

We'll match your existing stencil so you can start
saving money today!

RoHS/REACH Compliant
Conflict Mineral Free
UL & ISO 9001 Certified
Free DFM File Review
Prototypes to
Full Production

Company: HHMI

Contact: Peter Polidoro

Part Number: y_arena_valve_controller_v_1.2 Rev -

Email: polidorop@janelia.hhmi.org

Phone : Description :

Sides Silkscreen

Silkscreen Color

Gold Fingers

Quote Number

DW200804-1549

Date 8/5/2020 22:02

Gerber File Name y arena valve controller.zip

| Quoted PCB Specifications | | | | | | | | |
|---------------------------|------------------|-------|----|-------------------------|-----|--|--|--|
| Layers | 2 | | · | RoHS 3 Compliant | Yes | | | |
| - | 2.960 x | 3.180 | in | ITAR | No | | | |
| Array Size | 15.300 x | 6.860 | in | IPC Inspection Class | 2 | | | |
| Array | Yes | i | | REACH Compliant | Yes | | | |
| # In Array | 10 | | | UL/Date Code/94V-0 Mark | | | | |
| X-Outs Allowed? | Yes | | | Not Required | | | | |
| Scoring | Yes | # 9 | | Controlled Impedance | No | | | |
| Jump Scoring | No | | | Controlled Dielectric | No | | | |
| Tab Rout | No | | | Carbon Ink | No | | | |
| Material | FR-4 (135°C Tg) | | | Castellated Holes | No | | | |
| Final Thickness | 0.062in / 1.6mm | | | Blind/Buried Vias | No | | | |
| Plating | Lead Free Solder | | | Via in Pad | No | | | |
| Outer Cu Weight | 1 | | oz | Mask Tented Vias | No | | | |
| | | | | Mask Plugged Vias | No | | | |
| | | | | Conductive Filled Vias | No | | | |
| Sides Mask | Both | า | | Counter Sinks/Bores | No | | | |
| Mask Color | Gree | n | | Special Notes | | | | |

| Min Trace/Space | 8mil / 0.20mm |
|-------------------------|-----------------|
| Min Hole Size | >20mil / 0.50mm |
| # Holes Under 12 mil | 0 |
| Plated Slots | No |
| Plated Edges | No |

Both

White

No

Lead Times in Business Days (Mon-Fri)

| Bare PCB Unit Price | | | | | Qty per board not per array | | | |
|---------------------|---------|---------|---------|---------|-----------------------------|---------|--------|--------|
| Qty | 2 Day | 3 Day | 4 Day | 5 Day | 8 Day | 10 Day | 15 Day | 20 Day |
| 20 | \$31.43 | \$24.97 | \$23.09 | \$19.13 | \$15.27 | \$14.42 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

Bare Board Tooling: \$225 (Free) Bare Board Electrical Test: \$225 (Free)

| Assembly Labor Pricing Per UNIT | | | | | Additional Costs (price per Unit) | | |
|---------------------------------|-------|----------|-------------------|--------------------------|-----------------------------------|---------------------------------------|---------------------------------------|
| 1 Day | 2 Day | 5 Day | 10 Day | 15 Day | Parts | | |
| | | \$161.81 | \$135.10 | \$124.19 | \$105.86 | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | · | 1 Day 2 Day 5 Day | 1 Day 2 Day 5 Day 10 Day | 1 Day 2 Day 5 Day 10 Day 15 Day | 1 Day 2 Day 5 Day 10 Day 15 Day Parts | 1 Day 2 Day 5 Day 10 Day 15 Day Parts |

Assembly NRE: \$388

Free Bare Board Tooling and Electrical Test!

Free DFM (Design For Manufacturing) Review on Every Order

Ordering is Easy

To place an order, just call, email or fax me. I will be happy to place your order for you.

My direct contact information is below and at the top left of this page.

- Bare board fab and assembly are done at different facilities, there will be an additional 1 day in transit between them.
- Daily order cut off time is 9pm EST / 6pm PST. Day zero begins once files are approved by engineering. Quote valid for 30 days.
- Costs and lead times do not include shipping. Standard UPS Domestic Rates Apply. Quote valid for 30 days.

let us know immediately. It may not only affect the cost but also how your boards are constructed!

Figure 1 If certain specs were not specifically stated in your files, we assumed our industry standard specs. If any specs are inaccurate,

0 v-Prime 20.07.09