Report No.: PR-817 Customer: TURKEY

Shift: C (Night) Date: 11-05-2024

| Equipment | Operation | Worker | Begin | Finish | Time Spent | Comments | Condition |
|-----------|-----------|------------------------|-------|--------|------------|--------------|-------------|
| MC-205 | Cutting | Anna Nowak | 14:30 | 15:57 | 87 | Delay | Completed |
| MC-209 | Welding | Nadia Sauter | 12:15 | 13:44 | 89 | Recalibrated | In progress |
| MC-201 | Drilling | Wiktor Kopczyński | 13:00 | 13:55 | 55 | N/A | Completed |
| MC-208 | Drilling | Nadia Sauter | 10:30 | 11:34 | 64 | Delay | Completed |
| MC-202 | Drilling | Dawid Oszmiańczuk | 13:00 | 13:47 | 47 | Delay | In progress |
| MC-205 | Assembly | Magdalena Witkowska | 06:30 | 08:24 | 114 | ОК | Delayed |
| MC-204 | Welding | Wiktor Kopczyński | 13:15 | 13:39 | 24 | N/A | Delayed |

All production targets have been logged; deviations are highlighted above. Note any unscheduled stops in the downtime register. Archive this output summary for end-of-day reporting. Verify the final counts against inventory records. Ensure shift-handover notes include any pending issues.

| Part ID | Planned Qty | Produced Qty | Defect Qty | Failure % | Reworked Units | Uwagi |
|---------|-------------|-----------------|------------|-----------|-------------------|--------------------|
| RX-310Z | 116 | 114 | 2 | 1.72% | 10 | Scrap confirmed |
| LK-890B | 251 | 242 | 9 | 3.59% | 1 | |
| MS-600P | 268 | 231 | 37 | 13.81% | 2 | Scrap confirmed |
| AL-115Q | 104 | 89 | 15 | 14.42% | 0 | Rework needed |

| Approved by: | Prepared by: |
|--------------|---------------|
| Approved by. | i icpaica by. |