Equipment Record Report

Performed On: 2023-09-16

Authorized by:	Carlos Garcia
Operator:	Peter Schmidt

Refer to the maintenance register for detailed service histories. Entries include work orders, technician assignments, and part changes. All technician comments are recorded for maintenance trend analysis. The equipment log below includes fault codes and corrective notes. Use this record to plan upcoming upkeep and repairs. This maintenance extract is prepared for compliance audit trails.

Section A:

Unit Code	MC-280	MC-234	MC-219	MC-259	MC-206	MC-262
Machine	Laser Cutter	Laser Cutter	Lathe	Packaging Line	Assembly Robot	Paint Booth
Туре	Preventive	Corrective	Corrective	Corrective	Inspection	Corrective
Technician	Laura Rossi	Laura Rossi	Jan Kowalski	Carlos Garcia	Anna Nowak	Carlos Garcia
Downtime	1.9	3.7	2.4	2.6	2.9	3.2
Comments	Changed oil and filters.	Tightened loose bolts.	Alignment of hinges adjusted.	Alignment of hinges adjusted.	Sensor recalibrated.	Worn gasket replaced.

Section B:

Unit Code	MC-280	MC-259	MC-219	MC-213	MC-234	MC-226
Machine	Laser Cutter	Packaging	Lathe	Packaging	Laser Cutter	Hydraulic
		Line		Line		Press
Type	Inspection	Corrective	Inspection	Corrective	Corrective	Corrective
Technician	Peter Schmidt	Jan Kowalski	Laura Rossi	Laura Rossi	Laura Rossi	Carlos Garcia
Downtime	2.9	2.4	2.8	2.4	2.7	2.4
Comments	Replaced fuse (5A).	Refilled oil (HLP 46).	Li-lon battery pack serviced.	Calibration check OK.	Tightened loose bolts.	No issues found.

Uptime (%)	Error Count	Notes
93.30%	5	Replaced filter