## Machine Log Summary #7831570

Date: 2025-07-11

Unit Code	Equipment	Service Type	Operator	Downtime	Site	Notes
MC-255	Plasma Cutter	Corrective	Carlos Garcia	3.1	Plant 1C	Alignment of hinges adjusted.
MC-211	Conveyor Belt	Preventive	Peter Schmidt	1.9	Plant 1C	Li-lon battery pack serviced.
MC-201	Plasma Cutter	Preventive	Peter Schmidt	3.1	Plant 2B	Sensor recalibrated.
MC-238	Assembly Robot	Corrective	Jan Kowalski	3.8	Plant 2B	
MC-236	Hydraulic Press	Inspection	Anna Nowak	2.8	Plant 1C	Wooden pallet checked.
MC-205	Packaging Line	Inspection	Anna Nowak	4.0	Plant 3A	Replaced fuse (5A).
MC-209	Lathe	Inspection	Carlos Garcia	3.1	Plant 2B	Li-lon battery pack serviced.

Ensure next preventive service is scheduled according to plan. Check remaining life-cycles of key components from this report. Ensure that each service entry has the required approvals. Archive this summary in the CMMS for future reference. Record any spare parts usage for inventory adjustment.

Lubrication Checked	N/A
Calibration Verified	No
Emergency Stop Tested	N/A

Signed off:	Performed by:	