## **Machine Log Summary**

Performed On: 2025-06-12

Authorized by:	Carlos Garcia
Operator:	Peter Schmidt

Ensure all safety checks were completed during servicing. Use this record to plan upcoming upkeep and repairs. All technician comments are recorded for maintenance trend analysis. This maintenance extract is prepared for compliance audit trails. This section captures equipment status and any maintenance observations. Check that all downtime events are properly categorized and logged.

## Section A:

Machine ID	MC-221	MC-230	MC-238	MC-299	MC-252	MC-213
Equipment	Packaging Line	Lathe	Lathe	Lathe	Plasma Cutter	Paint Booth
Туре	Corrective	Inspection	Inspection	Preventive	Corrective	Corrective
Technician	Anna Nowak	Laura Rossi	Jan Kowalski	Anna Nowak	Jan Kowalski	Anna Nowak
Downtime	1.8	3.1	1.6	3.0	2.9	3.7
Notes		Sensor recalibrated.	Refilled oil (HLP 46).	Replaced fuse (5A).	Changed oil and filters.	Alignment of hinges
						adjusted.

## Section B:

Machine ID	MC-206	MC-299	MC-291	MC-237	MC-230	MC-252
Equipment	Assembly	Lathe	Packaging Line	CNC Milling	Lathe	Plasma Cutter
	Robot			Machine		
Туре	Corrective	Preventive	Corrective	Preventive	Inspection	Corrective
Technician	Laura Rossi	Carlos Garcia	Jan Kowalski	Laura Rossi	Laura Rossi	Anna Nowak
Downtime	3.3	3.9	2.1	1.9	1.7	2.7
Notes	Alignment of hinges adjusted.	Tightened loose bolts.	Replaced fuse (5A).	Worn gasket replaced.	Replaced fuse (5A).	Calibration check OK.

Overall equipment condition is satisfactory post-maintenance. All maintenance tasks have been completed as per schedule. Flag any recurring issues for root-cause investigation. Ensure that each service entry has the required approvals. Maintenance notes are archived for compliance audits.

Uptime (%)	Error Count	Notes
96.11%	4	Replaced filter