Quality Inspection List

	Inspection Checklist	Sampling	Defect Class			Observations	
	Points	Level					
С	Component Criteria		Critical	Major	Minor	OnHold	
1	Missing logo or warning label	Level II			V		Critical impact
2	Wood splinter or sharp point on product	Levell		V			
3	Paint smearing or scratches	Level III				V	Minor issue observed
4	Battery not included	Level III	V				Needs review
5	Incorrect barcode or label	Level III					Critical impact
6	Packaging does not match signed sample						Needs review
7	Connector not working						
8	Rubber Switch not working	Levell					Needs review
9	Missing safety labels	Level I				V	Minor issue observed
10	Dead or live insect in packaging	Levell					Critical impact

Reference Standards:

Standard	Edition
RoHS	2011
UL 61010	3rd Ed.