Equipment Record Report #1928796

Date: 2024-02-13

| Machine ID | Equipment | Туре | Operator | Downtime | Site | Notes |
|------------|------------------------|------------|---------------|----------|----------|--------------------------|
| MC-225 | Packaging Line | Corrective | Anna Nowak | 2.6 | Plant 1C | |
| MC-212 | Lathe | Inspection | Peter Schmidt | 2.2 | Plant 2B | |
| MC-222 | Conveyor Belt | Inspection | Anna Nowak | 3.6 | Plant 3A | Sensor recalibrated. |
| MC-262 | Plasma Cutter | Preventive | Carlos Garcia | 2.7 | Plant 2B | Sensor recalibrated. |
| MC-280 | CNC Milling Machine | Preventive | Jan Kowalski | 3.5 | Plant 1C | |
| MC-245 | CNC Milling Machine | Inspection | Carlos Garcia | 3.9 | Plant 1C | No issues found. |
| MC-254 | Conveyor Belt | Inspection | Anna Nowak | 3.5 | Plant 2B | Wooden pallet checked. |
| MC-207 | Paint Booth | Corrective | Carlos Garcia | 2.0 | Plant 1C | Sensor recalibrated. |
| MC-249 | Hydraulic Press | Inspection | Jan Kowalski | 1.7 | Plant 1C | |
| MC-294 | Assembly Robot | Corrective | Carlos Garcia | 2.6 | Plant 3A | Switch contacts cleaned. |

No critical faults were found during the latest inspection. Record any spare parts usage for inventory adjustment. This log summary supports the asset-management dashboard. Service summaries have been forwarded to the engineering team. Ensure next preventive service is scheduled according to plan.

| Lubrication Checked | N/A |
|-----------------------|-----|
| Calibration Verified | Yes |
| Emergency Stop Tested | N/A |

| Signed off: | Performed by: |
|-------------|---------------|
| Signed Off. | renonnea by. |