## **Equipment Record Report #9020340**

Date: 2023-12-29

Unit Code	Equipment	Service Type	Technician	Duration	Area	Notes
MC-290	Packaging Line	Preventive	Laura Rossi	1.9	Plant 3A	Replaced fuse (5A).
MC-242	Packaging Line	Inspection	Jan Kowalski	3.2	Plant 1C	Wooden pallet checked.
MC-277	CNC Milling Machine	Corrective	Peter Schmidt	2.0	Plant 3A	Worn gasket replaced.
MC-231	Laser Cutter	Inspection	Peter Schmidt	2.0	Plant 1C	Worn gasket replaced.
MC-235	Plasma Cutter	Corrective	Jan Kowalski	1.8	Plant 2B	Tightened loose bolts.
MC-228	Paint Booth	Inspection	Anna Nowak	3.9	Plant 2B	Wooden pallet checked.
MC-269	Paint Booth	Inspection	Laura Rossi	3.4	Plant 1C	Switch contacts cleaned.
MC-260	Laser Cutter	Corrective	Peter Schmidt	2.3	Plant 3A	Alignment of hinges adjusted.
MC-208	Lathe	Preventive	Carlos Garcia	2.4	Plant 1C	Replaced fuse (5A).

Archive this summary in the CMMS for future reference. Use this closure note to update the maintenance KPI tracker. Refer to remarks for any follow-up actions or parts replacements. Ensure that each service entry has the required approvals. Flag any recurring issues for root-cause investigation.

Lubrication Checked	N/A
Calibration Verified	No
Emergency Stop Tested	Yes

Authorized by:	Operator:	