Equipment Record Report #1001953

Date: 2024-03-14

Unit Code	Equipment	Туре	Technician	Downtime	Area	Comments
MC-285	CNC Milling	Corrective	Laura Rossi	2.6	Plant 1C	Tightened
	Machine					loose bolts.
MC-235	Laser Cutter	Preventive	Carlos Garcia	2.8	Plant 3A	Wooden pallet
						checked.
MC-229	Plasma Cutter	Inspection	Carlos Garcia	3.3	Plant 3A	
MC-231	Assembly	Corrective	Anna Nowak	3.1	Plant 1C	Li-lon battery
	Robot					pack serviced.
MC-295	Plasma Cutter	Corrective	Peter Schmidt	4.0	Plant 2B	Replaced
						coolant.
MC-251	Assembly	Inspection	Laura Rossi	2.1	Plant 1C	Refilled oil (HLP
	Robot					46).
MC-283	Hydraulic Press	Inspection	Jan Kowalski	3.1	Plant 3A	
MC-279	Conveyor Belt	Preventive	Laura Rossi	2.2	Plant 3A	Wooden pallet
						checked.
MC-248	Hydraulic Press	Preventive	Peter Schmidt	3.8	Plant 2B	Sensor
						recalibrated.

All maintenance tasks have been completed as per schedule. Refer to remarks for any follow-up actions or parts replacements. Service summaries have been forwarded to the engineering team. Ensure next preventive service is scheduled according to plan.

Lubrication Checked	No
Calibration Verified	N/A
Emergency Stop Tested	Yes

Approved by:	Serviced by:	