Equipment Record Report

Performed On: 2023-12-26

Authorized by:	Peter Schmidt
Operator:	Peter Schmidt

All technician comments are recorded for maintenance trend analysis. Use this summary to forecast parts replacement and resource needs. Use this record to plan upcoming upkeep and repairs. Below is the summary of service actions and downtimes for each machine. Please review this log for recent service dates, types, and remarks. This maintenance extract is prepared for compliance audit trails.

Section A:

Machine ID	MC-215	MC-275	MC-209	MC-285	MC-241	MC-247
Equipment	Hydraulic	Conveyor Belt	CNC Milling	Assembly	Laser Cutter	Lathe
	Press		Machine	Robot		
Туре	Preventive	Preventive	Corrective	Corrective	Corrective	Preventive
Technician	Peter Schmidt	Peter Schmidt	Carlos Garcia	Laura Rossi	Jan Kowalski	Anna Nowak
Downtime	3.2	3.0	2.4	3.7	2.8	1.6
Notes	No issues	Replaced fuse	Tightened	Alignment of	Worn gasket	Switch
	found.	(5A).	loose bolts.	hinges	replaced.	contacts
				adjusted.		cleaned.

Section B:

Machine ID	MC-280	MC-243	MC-209	MC-290	MC-241	MC-285
Equipment	CNC Milling	Plasma Cutter	CNC Milling	Assembly	Laser Cutter	Assembly
	Machine		Machine	Robot		Robot
Туре	Inspection	Preventive	Preventive	Preventive	Preventive	Inspection
Technician	Jan Kowalski	Laura Rossi	Laura Rossi	Carlos Garcia	Laura Rossi	Peter Schmidt
Downtime	2.4	3.4	1.6	2.7	2.9	3.0
Notes	No issues	Tightened	Calibration	Sensor	Sensor	Worn gasket
	found.	loose bolts.	check OK.	recalibrated.	recalibrated.	replaced.

Uptime (%)	Error Count	Comments
90.10%	4	Bolt tightened