Equipment Record Report #1046724

Date: 2023-11-26

Unit Code	Equipment	Service Type	Technician	Downtime	Area	Notes
MC-207	Plasma Cutter	Preventive	Laura Rossi	2.4	Plant 3A	Alignment of hinges adjusted.
MC-262	Packaging Line	Corrective	Anna Nowak	3.2	Plant 3A	Replaced fuse (5A).
MC-288	Laser Cutter	Corrective	Laura Rossi	3.5	Plant 1C	
MC-266	Assembly Robot	Corrective	Peter Schmidt	2.7	Plant 1C	Worn gasket replaced.
MC-220	Laser Cutter	Corrective	Laura Rossi	1.9	Plant 2B	
MC-215	Laser Cutter	Preventive	Peter Schmidt	3.2	Plant 3A	Calibration check OK.
MC-231	Hydraulic Press	Corrective	Anna Nowak	2.6	Plant 2B	Tightened loose bolts.
MC-286	Lathe	Inspection	Laura Rossi	3.1	Plant 3A	Sensor recalibrated.

Maintenance notes are archived for compliance audits. Archive this summary in the CMMS for future reference. Confirm that all corrective actions were properly closed out. Overall equipment condition is satisfactory post-maintenance. Flag any recurring issues for root-cause investigation. All maintenance tasks have been completed as per schedule.

Lubrication Checked	N/A
Calibration Verified	Yes
Emergency Stop Tested	No

Approved by:	Serviced by:	