Authorized by:	Carlos Garcia
Operator:	Carlos Garcia

Use this record to plan upcoming upkeep and repairs. The equipment log below includes fault codes and corrective notes. Check that all downtime events are properly categorized and logged. Below is the summary of service actions and downtimes for each machine. Use this summary to forecast parts replacement and resource needs. Confirm that service intervals follow the preventive schedule.

## Section A:

Unit Code	MC-270	MC-249	MC-208	MC-281	MC-286	MC-204
Machine	Lathe	Lathe	CNC Milling	Plasma Cutter	Plasma Cutter	Packaging
			Machine			Line
Service Type	Inspection	Corrective	Preventive	Preventive	Corrective	Inspection
Operator	Anna Nowak	Peter Schmidt	Carlos Garcia	Jan Kowalski	Peter Schmidt	Carlos Garcia
Duration	2.0	3.4	3.4	2.8	3.3	4.0
Notes		Sensor recalibrated.	Replaced fuse (5A).	Refilled oil (HLP 46).	Worn gasket replaced.	Refilled oil (HLP 46).

## Section B:

Unit Code	MC-237	MC-270	MC-243	MC-281	MC-208	MC-204
Machine	Paint Booth	Lathe	Packaging	Plasma Cutter	CNC Milling	Packaging
			Line		Machine	Line
Service Type	Inspection	Inspection	Corrective	Corrective	Preventive	Preventive
Operator	Carlos Garcia	Laura Rossi	Laura Rossi	Anna Nowak	Carlos Garcia	Jan Kowalski
Duration	2.1	2.4	2.7	3.4	3.8	2.6
Notes	Sensor	Worn gasket	Sensor	Alignment of	Switch	Li-lon battery
	recalibrated.	replaced.	recalibrated.	hinges	contacts	pack serviced.
				adjusted.	cleaned.	

Ensure next preventive service is scheduled according to plan. Check remaining life-cycles of key components from this report.

Uptime (%)	Error Count	Comments
92.04%	3	Replaced filter