## **Equipment Record Report #3110432**

Date: 2025-07-01

Unit Code	Machine	Service Type	Technician	Duration	Site	Comments
MC-204	Lathe	Preventive	Carlos Garcia	2.0	Plant 2B	Replaced fuse (5A).
MC-251	Plasma Cutter	Inspection	Peter Schmidt	3.8	Plant 2B	Wooden pallet checked.
MC-231	Paint Booth	Preventive	Anna Nowak	3.3	Plant 1C	Calibration check OK.
MC-240	Packaging Line	Preventive	Laura Rossi	2.7	Plant 3A	Wooden pallet checked.
MC-249	Conveyor Belt	Inspection	Carlos Garcia	2.7	Plant 1C	Changed oil and filters.
MC-256	Packaging Line	Preventive	Jan Kowalski	2.8	Plant 1C	No issues found.
MC-214	Lathe	Inspection	Jan Kowalski	1.8	Plant 1C	Refilled oil (HLP 46).
MC-269	CNC Milling Machine	Inspection	Anna Nowak	2.4	Plant 2B	Switch contacts cleaned.
MC-267	Lathe	Corrective	Jan Kowalski	2.8	Plant 3A	No issues found.

Ensure that each service entry has the required approvals. This log summary supports the asset-management dashboard. Check remaining life-cycles of key components from this report. Service summaries have been forwarded to the engineering team. Flag any recurring issues for root-cause investigation.

Lubrication Checked	N/A
Calibration Verified	Yes
Emergency Stop Tested	N/A

Authorized by:	Operator: